

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Not Notified
U/Pay @ 3150k
Paying After Repair
4 days

Vehicle Number : SNG 9758K

Date: 16.11.24

S/N Parts Description

Unit Price Amt

- 1 Rear tailgate
- 2 Rear tailgate Shuttle emblem
- 3 Rear tailgate Hybrid emblem
- 4 Rear tailgate emblem
- 5 Rear tailgate outer garnish
- 6 Rear tailgate lock
- 7 Rear tailgate rubber
- 8 Rear tailgate inner board
- 9 Rear tailgate windscreen mldg
- 9 Rear bumper
- 10 Rear bumper retainer X 2
- 11 Rear bumper inner bracket LH
- 12 Rear bumper reflector X 2
- 13 Rear bumper chrome mldg
- 14 Taillamp LH & RH
- 15 Rear end panel
- 16 Rear end panel top garnish

Pr	\$1,295.00	✓
na	\$95.00	—
na	\$96.00	—
na	\$68.00	X
ln	\$286.20	X
na	\$299.00	—
Adi/Di	\$186.00	✓
ln	\$350.40	X
na	\$121.60	✓
Bu	\$936.00	✓
\$42.50	ln	\$85.00 X
	n	\$132.00 X
\$76.80	ln	\$153.60 X
	Ad	\$126.90 ✓
\$592.30	ln	\$1,184.60 X
	R	\$681.00 X
	ln	\$155.80 X

201

Special Nett

- 1 Rear bumper clips
- 2 Rear No. plate
- 3 Rear windscreen sealant
- 4 Rear bumper reverse sensor

na	\$50.00	✓
ln	\$60.00	X
na	\$80.00	401m
ln	\$300.00	X

Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas.
- 2 To spray paint on affected areas.
- 3 To remove and refit rear windscreen
- 4 To remove and refit reverse sensor
- 5 Check wiring
- 6 Tuff coating

\$1000.00	500l
\$1,000.00	600l
\$200.00	120l
\$100.00	50l
\$50.00	15l
\$120.00	30l

\$2,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: