

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 04.11.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SLF5579R
MODEL : KIA FORTE K3
DATE OF ACCIDENT : 20.10.2024
TIME OF ACCIDENT : 18:40 HOURS

Daphne

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 668.00	\$ 668.00
2	FRONT BUMPER TOP RUBBER <i>new</i>	1	\$ 43.00	\$ 43.00
3	FRONT BUMPER GRILLE CHROME <i>new</i>	1	\$ 276.00	\$ 276.00
4	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 79.00	\$ 79.00
5	FRONT BUMPER FOGLAMP LH <i>cracked</i>	1	\$ 268.00	\$ 268.00
6	FRONT BUMPER FOGLAMP COVER GARNISH LH	1	\$ 23.00	\$ 23.00
7	FRONT BUMPER SENSOR LH <i>new</i>	2	\$ 195.00	\$ 390.00
8	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 17.00	\$ 34.00
9	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 421.00	\$ 421.00
10	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 123.00	\$ 123.00
11	FRONT FENDER INNER COWLING LH <i>new</i>	1	\$ 109.00	\$ 109.00
12	HEAD LAMP (HID) <i>LH cracked</i>	2	\$ 1,870.00	\$ 3,740.00
13	HEAD LAMP LOWER BRACKET <i>new</i>	2	\$ 45.00	\$ 90.00
14	BONNET <i>new</i>	1	\$ 877.00	\$ 877.00
15	BONNET LOCK <i>new</i>	1	\$ 65.00	\$ 65.00
16	BONNET STOPPER <i>new</i>	1	\$ 21.00	\$ 21.00
17	FRONT SUPPORT PANEL	1	\$ 776.00	\$ 776.00
18	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 53.00	\$ 53.00
19	FRONT SUPPORT PANEL LOWER GARNISH <i>new</i>	1	\$ 110.00	\$ 110.00
20	FRONT AIRCON CONDENSER SIDE GARNISH <i>new</i>	2	\$ 21.00	\$ 42.00

TOTAL PRICE \$ 8,208.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLF5579R
 MODEL : KIA FORTE K3
 DATE OF ACCIDENT : 20.10.2024
 TIME OF ACCIDENT : 18:40 HOURS

2929
 2636-10

LESS 10% \$ 820.80
 SUB TOTAL PRICE \$ 7,387.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Not nee</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00
3	BONNET SEALANT <i>Not nee</i>	1	\$ 150.00	\$ 150.00
4	BONNET INSULATOR CLIP (SET) <i>Not nee</i>	1	\$ 50.00	\$ 50.00
5	CENTER GRILLE CLIP (SET) <i>Not nee</i>	1	\$ 30.00	\$ 30.00
6	FRONT FENDER INNER COWLING CLIP (SET) <i>Not nee</i>	1	\$ 60.00	\$ 60.00
7	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>Not nee</i>	1	\$ 30.00	\$ 30.00
8	FRONT AIRCON CONDENSER SIDE GARNISH CLIP (SET) <i>Not nee</i>	1	\$ 30.00	\$ 30.00
9	COOLANT <i>Not nee</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 540.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	200
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	X
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X
5	REFOCUS HEADLAMP BEAM	\$ 60.00	X
6	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING	\$ 80.00	50

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SLF5579R
MODEL : KIA FORTE K3
DATE OF ACCIDENT : 20.10.2024
TIME OF ACCIDENT : 18:40 HOURS

7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
---	--	-----------	---

550

TOTAL \$ 2,720.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,927.20
TOTAL LABOUR COST : \$ 2,720.00
TOTAL REPAIR COST : \$ 10,647.20

Adrian King,
2/s 12/11/24
03 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 3216.10
4/s 2550 ✓

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
