



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2502054

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 04/04/2025  
Reference CD/CTI24110434/Ama3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SMC 7045E  
Insured Veh. SLU 8399U  
Claim No. SNM24D206409  
Policy No. DMHCSNA0006192401  
Accident Date 13/11/2024  
Inspection Date 14/11/2024

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (9%)</b>                | <b>36.00</b>  |
| <b>Grand Total</b>             | <b>436.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |                                                                                                                                        |                                                                                                      |                               |            |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-------------------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909 |                                                                                                                                        |                                                                                                      | Ref: CD/CTI24110434/Ama3q2(N) |            |
|                                                                                                |                                                                                                                                        |                                                                                                      | Date: 04/04/2025              |            |
|                                                                                                |                                                                                                                                        |                                                                                                      | Code: CTI                     |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                              |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | Insured Veh.                                                                                                                           | SLU 8399U                                                                                            | Veh. Inspected                | SMC 7045E  |
|                                                                                                | Policy No.                                                                                                                             | DMHCSNA0006192401                                                                                    | Coverage (\$)                 | 0.00       |
|                                                                                                | Claim No.                                                                                                                              | SNM24D206409                                                                                         | Excess (\$)                   | 0.00       |
|                                                                                                | Assign From                                                                                                                            |                                                                                                      | Assign Date                   | 14/11/2024 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                  |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | Make & Model                                                                                                                           | MITSUBISHI ECLIPSE CROSS                                                                             | c.c                           | 1499       |
|                                                                                                | Engine No.                                                                                                                             | HIDDEN                                                                                               | Year of Reg.                  | 2018       |
|                                                                                                | Chassis No.                                                                                                                            | JMAXTGK1WJZ001360                                                                                    | Colour                        | WHITE      |
|                                                                                                | Odometer                                                                                                                               | 54294 KM                                                                                             | Steering                      | IN ORDER   |
|                                                                                                | Brakes                                                                                                                                 | IN ORDER                                                                                             | Modification                  | SPORTS RIM |
|                                                                                                | General                                                                                                                                | GOOD                                                                                                 |                               |            |
| <b>3. Conditions of Tyres</b>                                                                  |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                |                                                                                                                                        | Size                                                                                                 | Make                          | Balance    |
|                                                                                                | R/H Front Tyre                                                                                                                         | 225/55 R18                                                                                           | ROADSTONE                     | 6 mm       |
|                                                                                                | L/H Front Tyre                                                                                                                         | 225/55 R18                                                                                           | ROADSTONE                     | 6 mm       |
|                                                                                                | R/H Rear Tyre                                                                                                                          | 225/55 R18                                                                                           | ROADSTONE                     | 6 mm       |
|                                                                                                | L/H Rear Tyre                                                                                                                          | 225/55 R18                                                                                           | ROADSTONE                     | 6 mm       |
| <b>4. Description of Damages</b>                                                               |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.<br><br>DAMAGES SEE DETAILS.                                                 |                                                                                                      |                               |            |
| <b>5. General Information</b>                                                                  |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | Accident Date                                                                                                                          | 13/11/2024                                                                                           | Inspection Date               | 14/11/2024 |
|                                                                                                | Survey held at                                                                                                                         | HD PERFECT AUTOWORK PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                               |            |
| <b>5a. Remarks</b>                                                                             |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                      |                               |            |
| <b>5b. Estimate Days of Repair</b>                                                             |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                      | 9 Working Days                |            |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 7045E

| Qty | Description of Parts                                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                   |                      |                           |                   |
| 1   | FRONT BUMPER                                         | DEFORMED             | 846.00                    | 718.00            |
| 1   | FRONT BUMPER LOWER DIFFUSER                          | DAMAGED              | 431.00                    | 431.00            |
| 2   | FRONT BUMPER SIDE RETAINER @\$72.00                  | NOT NECESSARY        | 144.00                    | -                 |
| 2   | FRONT BUMPER LAMP @\$568.30                          | O/S CRACKED          | 1,136.60                  | 568.30            |
| 2   | FRONT BUMPER LAMP BRACKET @\$298.10                  | NOT NECESSARY        | 596.20                    | -                 |
| 1   | FRONT BUMPER LAMP WIRE HARNESS                       | NOT NECESSARY        | 760.00                    | -                 |
| 1   | FRONT BUMPER CENTER GARNISH                          | DEFORMED             | 487.30                    | 487.30            |
| 1   | FRONT CENTER GRILLE BASE                             | CRACKED              | 413.60                    | 413.60            |
| 1   | FRONT CENTER GRILLE LOGO                             | NECESSARY            | 89.00                     | 89.00             |
| 2   | FRONT BUMPER SIDE CHROME MOULDING (UPPER) @ \$460.00 | O/S CRACKED          | 920.00                    | 480.00            |
| 2   | FRONT BUMPER SIDE CHROME MOULDING (LOWER) @ \$410.00 | CRACKED              | 820.00                    | 820.00            |
| 2   | FRONT BUMPER SIDE ARCH GARNISH @\$151.00             | NOT NECESSARY        | 302.00                    | -                 |
| 1   | FRONT BUMPER BOTTOM COVER                            | NOT NECESSARY        | 240.00                    | -                 |
| 1   | FRONT BUMPER REINFORCEMENT                           | NOT NECESSARY        | 552.00                    | -                 |
| 1   | FRONT BUMPER UPPER BEAM                              | NOT NECESSARY        | 135.00                    | -                 |
| 2   | FRONT BUMPER UPPER BEAM BRACKET @\$81.00             | NOT NECESSARY        | 162.00                    | -                 |
| 2   | FRONT BUMPER UPPER BEAM SUPPORT BRACKET @ \$73.00    | NOT NECESSARY        | 146.00                    | -                 |
| 1   | FRONT BUMPER UPPER BEAM COVER GARNISH                | NOT NECESSARY        | 113.00                    | -                 |
| 1   | FRONT BUMPER LOWER BEAM                              | NOT NECESSARY        | 235.00                    | -                 |
| 1   | FRONT SUPPORT PANEL                                  | TO REPAIR SEE LABOUR | 898.00                    | -                 |
| 1   | FRONT SUPPORT TOP GARNISH                            | NOT NECESSARY        | 185.00                    | -                 |
| 2   | FRONT FENDER INNER COWLING @\$134.20                 | NOT NECESSARY        | 268.40                    | -                 |
| 2   | HEADLAMP (HID) @\$2145.90                            | CRACKED              | 4,291.80                  | 4,291.80          |
| 2   | HORN @\$130.00                                       | NOT NECESSARY        | 260.00                    | -                 |
| 1   | TURBO INTER COOLER                                   | NOT NECESSARY        | 1,310.00                  | -                 |
| 1   | AIRCON CONDENSOR                                     | NOT NECESSARY        | 1,620.00                  | -                 |
| 2   | AIRCON PIPE @\$960.00                                | NOT NECESSARY        | 1,920.00                  | -                 |
| 2   | AIR CON CONDENSER SIDE GARNISH @\$195.00             | NOT NECESSARY        | 390.00                    | -                 |

Report Ref No. CD/CTI24110434/Ama3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------|---------------|---------------------------|-------------------|
| 1   | OUTSIDE TEMPERATURE SENSOR                 | NOT NECESSARY | 290.00                    | -                 |
| 1   | REAR BUMPER                                | DEFORMED      | 832.00                    | 605.00            |
| 2   | REAR BUMPER LAMP @\$201.50                 | O/S CRACKED   | 403.00                    | 201.50            |
| 1   | REAR BUMPER LAMP WIRE HARNESS              | NOT NECESSARY | 121.00                    | -                 |
| 1   | REAR BUMPER CENTRE (BLACK)                 | DEFORMED      | 353.50                    | 353.50            |
| 2   | REAR BUMPER RETAINER @\$58.00              | NOT NECESSARY | 116.00                    | -                 |
| 1   | REAR BUMPER REINFORCEMENT                  | DENTED        | 594.00                    | 594.00            |
| 2   | REAR BUMPER SPONGE                         | O/S CRACKED   | 330.60                    | 165.30            |
| 2   | REAR BUMPER BRACKET @\$48.00               | O/S BENT      | 96.00                     | 48.00             |
| 2   | REAR BUMPER CENTER LOWER GARNISH @\$138.00 | O/S DEFORMED  | 276.00                    | 138.00            |
| 2   | REAR FENDER INNER COWLING (REAR) @\$119.00 | NOT NECESSARY | 238.00                    | -                 |
| 1   | REAR FENDER INNER TRIM RH                  | CRACKED       | 329.00                    | 329.00            |
| 2   | TAILLAMP @\$869.00                         | NOT NECESSARY | 1,738.00                  | -                 |
| 1   | TAILGATE                                   | DENTED        | 1,586.20                  | 942.00            |
| 1   | TAILGATE LOGO                              | NOT NECESSARY | 98.30                     | -                 |
| 1   | TAILGATE EMBLEM ECLIPSE                    | NOT NECESSARY | 84.60                     | -                 |
| 1   | TAILGATE EMBLEM CROSS                      | NOT NECESSARY | 83.50                     | -                 |
| 1   | TAILGATE EMBLEM MIVEC                      | NOT NECESSARY | 95.60                     | -                 |
| 2   | TAILGATE STOPPER @\$18.00                  | O/S MISSING   | 36.00                     | 18.00             |
| 1   | TAILGATE TOP LOCK                          | DAMAGED       | 439.50                    | 289.00            |
| 1   | TAILGATE LOWER LOCK                        | NOT NECESSARY | 68.00                     | -                 |
| 1   | TAILGATE WEATHERSTRIP                      | TORN          | 329.00                    | 329.00            |
| 1   | TAILGATE DETECTOR (OUTER)                  | CRACKED       | 235.60                    | 235.60            |
| 1   | TAILGATE DETECTOR (INNER)                  | NOT NECESSARY | 235.60                    | -                 |
| 1   | TAILGATE BUZZER                            | NOT NECESSARY | 186.20                    | -                 |
| 1   | REAR END PANEL                             | DENTED        | 528.00                    | 528.00            |
| 1   | REAR END PANEL TOP GARNISH                 | DEFORMED      | 219.00                    | 219.00            |
| 1   | REAR FLOOR PANEL TOP BOARD                 | DEFORMED      | 548.00                    | 548.00            |
| 1   | REAR STORAGE BOX (PLASTIC)                 | DEFORMED      | 164.90                    | 164.90            |
| 1   | REAR EXHAUST BOX                           | DENTED        | 679.00                    | 679.00            |
| 1   | REAR EXHAUST INSULATOR                     | NOT NECESSARY | 155.00                    | -                 |
| 1   | REAR EXHAUST GASKET                        | NOT NECESSARY | 86.00                     | -                 |
| 2   | REAR EXHAUST MOUNTING @\$24.00             | NOT NECESSARY | 48.00                     | -                 |

Report Ref No. CD/CTI24110434/Ama3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts                                                                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | LESS 10% DISCOUNT                                                                                    |               | -3,129.50                 | -1,468.58         |
|     |                                                                                                      |               | 28,165.50                 | 13,217.22         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                     |               |                           |                   |
| 1   | FRONT NUMBER PLATE (SN)                                                                              | BENT          | 50.00                     | 50.00             |
| 1   | SET FRONT BUMPER CLIP (SN)                                                                           | NECESSARY     | 50.00                     | 30.00             |
| 1   | SET FRONT BUMPER BOTTOM COVER TOP GARNISH CLIP (SN)                                                  | NOT NECESSARY | 30.00                     | -                 |
| 1   | SET FRONT FENDER COWLING CLIP (SN)                                                                   | NOT NECESSARY | 60.00                     | -                 |
| 1   | SET FRONT GRILLE CLIP (SN)                                                                           | NECESSARY     | 30.00                     | 30.00             |
| 1   | SET AIR CON CONDENSOR SIDE GARNISH CLIP (SN)                                                         | NOT NECESSARY | 30.00                     | -                 |
| 1   | FRONT PANEL SUPPORT SEALANT (SN)                                                                     | NOT NECESSARY | 60.00                     | -                 |
| 1   | SET FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)                                                        | NOT NECESSARY | 30.00                     | -                 |
| 1   | RADIATOR COOLANT (SN)                                                                                | NOT NECESSARY | 80.00                     | -                 |
| 1   | REAR NUMBER PLATE (SN)                                                                               | NOT NECESSARY | 80.00                     | -                 |
| 1   | SET REAR BUMPER CLIP (SN)                                                                            | NECESSARY     | 80.00                     | 30.00             |
| 1   | SET REAR BUMPER INNER TRIM CLIP (SN)                                                                 | NOT NECESSARY | 80.00                     | -                 |
| 1   | SET TAILGATE INSULATOR CLIP (SN)                                                                     | NOT NECESSARY | 80.00                     | -                 |
| 1   | TAILGATE WINDSCREEN SEALANT (SN)                                                                     | NECESSARY     | 120.00                    | 40.00             |
| 1   | TAILGATE WINDSCREEN INNER SHIELD (SN)                                                                | NECESSARY     | 120.00                    | 30.00             |
| 1   | TAILGATE EMBLEM 'C&C'                                                                                | NOT NECESSARY | 80.00                     | -                 |
| 1   | SET TAIL LAMP CLIP (SN)                                                                              | NOT NECESSARY | 60.00                     | -                 |
| 1   | SET REAR FENDER INNER COWLING CLIP (SN)                                                              | NOT NECESSARY | 80.00                     | -                 |
| 1   | SET REAR FENDER INNER TRIM CLIPS (SN)                                                                | NECESSARY     | 80.00                     | 60.00             |
| 1   | SET REAR END PANEL TOP GARNISH CLIP (SN)                                                             | NECESSARY     | 40.00                     | 20.00             |
| 1   | REAR END PANEL INSULATION SEALANT (SN)                                                               | NECESSARY     | 150.00                    | 60.00             |
| 1   | REVERSE SENSOR (SN)                                                                                  | DAMAGED       | 220.00                    | 200.00            |
|     |                                                                                                      |               | 1,690.00                  | 550.00            |
|     | <b><u>LABOUR</u></b>                                                                                 |               |                           |                   |
|     | PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL . (FRONT) |               | 1,800.00                  | 400.00            |
|     | SPRAY PAINTING TO AFFECTED AREA.(FRONT)                                                              |               | 1,800.00                  | 200.00            |
|     | TUFF COAT.(FRONT)                                                                                    | NOT NECESSARY | 250.00                    | -                 |

Report Ref No. CD/CTI24110434/Ama3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty                | Description of Parts                                                                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|--------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                    | WIRING CHECK .(FRONT)                                                                                  |               | 250.00                    | 30.00             |
|                    | REFOCUS HEADLAMP BEAM .(FRONT)                                                                         | NOT NECESSARY | 60.00                     | -                 |
|                    | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR .(FRONT)               | NOT NECESSARY | 250.00                    | -                 |
|                    | REMOVE AND REFIX INTER COOLER.(FRONT)                                                                  | NOT NECESSARY | 80.00                     | -                 |
|                    | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS .(FRONT)                                       | NOT NECESSARY | 120.00                    | -                 |
|                    | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST .(FRONT)                                           | NOT NECESSARY | 80.00                     | -                 |
|                    | PANEL BEATING ,REMOVAL AND REPLACING PARTS. (REAR)                                                     |               | 1,800.00                  | 700.00            |
|                    | TO SPRAY PAINT AFFECTED AREA. (REAR)                                                                   |               | 1,600.00                  | 700.00            |
|                    | TUFF COAT. (REAR)                                                                                      |               | 250.00                    | 60.00             |
|                    | WIRING CHECK . (REAR)                                                                                  |               | 180.00                    | 30.00             |
|                    | REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR . (REAR)                              |               | 350.00                    | 60.00             |
|                    | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING. (REAR)                                           |               | 80.00                     | 50.00             |
|                    | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING. (REAR)                                           |               | 80.00                     | 50.00             |
|                    | REAR CHASSIS ALIGNMENT . (REAR)                                                                        | NOT NECESSARY | 250.00                    | -                 |
|                    | CONDUCT WATER LEAKAGE TEST . (REAR)                                                                    | NOT NECESSARY | 120.00                    | -                 |
|                    | TRANSFER BOOTLID MECHANISM. (REAR)                                                                     |               | 80.00                     | 60.00             |
|                    | REMOVE AND REFIX TAILGATE WINDSCREEN. (REAR)                                                           |               | 120.00                    | 120.00            |
|                    | REMOVE AND REFIX REAR EXHAUST PIPE . (REAR)                                                            |               | 180.00                    | 60.00             |
|                    | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC. (REAR) | NOT NECESSARY | 250.00                    | -                 |
|                    |                                                                                                        |               | 10,030.00                 | 2,520.00          |
| <b>GRAND TOTAL</b> |                                                                                                        |               | <b>39,885.50</b>          | <b>16,287.22</b>  |

|                                                                             |  |  |                  |
|-----------------------------------------------------------------------------|--|--|------------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>13,000.00</b> |
|-----------------------------------------------------------------------------|--|--|------------------|

Report Ref No. CD/CTI24110434/Ama3q2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)

### PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**INSPECTION PHOTOS (Page 8 of 8)**

### PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**




**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**



**PHOTOGRAPHS FOR VEHICLE NO. : SMC 7045E**

