



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2507887

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN: SERENE LER

INV Date 18/11/2025
Reference CD/FCI24110437/Rua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNG 7407L
Insured Veh. SHD 3640S
Claim No. D24010194MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 18/11/2024
Inspection Date 21/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CD/FCI24110437/Rua3q2	
		Date:	18/11/2025	
		Code:	FCI2	
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHD 3640S	Veh. Inspected	SNG 7407L	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24010194MFCT/CTPL/TPD 2	Excess	\$0.00	
Assign From	SERENE LER	Assign Date	21/11/2024	
2. Vehicle Details				
Make & Model	VOLKSWAGEN GOLF 1.5 LIFE PLUS ETSI	C.C	1498	
Engine No.	DFY407426	Year of Reg.	30/08/2022	
Chassis No.	WVWZZZCDZNW164539	Colour	GREY	
Odometer	41809 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	225/40 R18	BRIDGESTONE	6	
L/H Front Tyre	225/40 R18	BRIDGESTONE	6	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2024	Inspection Date	21/11/2024	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNG 7407L

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR VIEW MIRROR HOUSING (SN)	CRACKED	\$880.64	\$880.64
1	MIRROR GLASS (SN)	SERVICEABLE	\$147.12	\$0.00
1	MIRROR CAP PRIMED (SN)	CRACKED	\$153.05	\$153.05
1	WARNING DISPLAY FOR LANE (SN)	NOT NECESSARY	\$170.77	\$0.00
1	WINDOW SLOT SEAL BLACK LHS FRT DOOR GLASS OUTER MLDG (SN)	CUT	\$97.50	\$97.50
1	ALLOY WHEEL ALUMINIUM SHI (SN)	CUT	\$1,977.51	\$1,977.51
1	RUBBER VALVE (SN)	NECESSARY	\$4.27	\$4.27
1	FENDER LH (SN)	BENT	\$1,142.98	\$1,142.98
3	RIVETTED CAP NUT (SN)	NECESSARY	\$8.70	\$8.70
1	GUIDE PIECE FRT BUMPER SIDE BRACKER LH (SN)	SERVICEABLE	\$56.74	\$0.00
			\$4,639.28	\$4,264.65

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	B&P CHECK SPORT CIRCUIT/HARNESS REPAIR		\$280.00	\$280.00
	B&P DIAGNOSIS AND PROGRAMMING		\$480.00	\$480.00
	B&P WHEEL ALIGNMENT		\$360.00	\$360.00
	R&R RIM & BALANCING		\$50.00	\$50.00
	360 CAMERA CALIBRATION		\$840.00	\$840.00
	LABOUR		\$3,360.00	\$1,680.00
	SPRAY PAINT		\$4,000.00	\$1,600.00
	SPRAY MIRROR COVER		\$280.00	\$280.00
			\$9,650.00	\$5,570.00

GRAND TOTAL			\$14,289.28	\$9,834.65
--------------------	--	--	--------------------	-------------------

	RECOMMENDED COST OF REPAIRS		\$9,834.65
--	------------------------------------	--	-------------------

Report Ref No: CD/FCI24110437/Rua3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 18)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 13 of 18)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7407L

