

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____
 (Policy Condition)

N/S	O/S

Remark: Vehicle had commenced its repair at the time of inspection.

Bel. or Market Value: _____
 IDAC Accident Report _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKA80912 Yr Regn: 2009, June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Camry C.D. 2362
 Colour: Gold A/C: Insured / Std / NI / NA
 Sp. Reading: 902229 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: M.R053BK4007034763
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Blackhawk

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 02/12/24
 Survey held at M6 Solution
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Claim</u>
	<u>COE Expiry: 09/06/2029.</u>
	<u>Estimate given during: Yes (✓)</u>
	<u>1st Survey: No ()</u>
	<u>MV: 871K</u>
	<u>PV: 19.4K</u>
	<u>Nett: 17.6K</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Report Form: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)

Survey Fee:	
Transportation:	
B + RS: \$1	
Photos	
Others	

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	02-12-24
CLAIM TYPE:	T/P CLAIM
TO:	CHINA TAIPING
VEHICLE DETAILS	
VEHICLE NO:	SKA8019Z
MAKE & MODEL:	TOYOTA CAMRY 2.4
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	8 November, 2024
TIME:	1750HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOTLID	1	\$ 1,255.60	\$ 1,255.60
2	REAR BOOTLID LOGO	1	\$ 90.00	\$ 90.00
3	REAR BOOTLID CAMRY EMBLEM	1	\$ 80.00	\$ 80.00
4	REAR BOOTLID 2.4 EMBLEM	1	\$ 80.00	\$ 80.00
5	REAR BOOTLID LOCK	1	\$ 420.00	\$ 420.00
6	REAR BOOTLID WEATHERSTRIP	1	\$ 250.00	\$ 250.00
7	REAR BOOTLID ANTENNA SWITCH	1	\$ 190.00	\$ 190.00
8	NUMBER PLATE OUTER GARNISH	1	\$ 580.00	\$ 580.00
9	REAR BUMPER	1	\$ 890.00	\$ 890.00
10	REAR BUMPER SIDE RETAINER	2	\$ 62.40	\$ 124.80
11	REAR BUMPER REINFORCEMENT	1	\$ 480.00	\$ 480.00
12	REAR BUMPER REFLECTOR	2	\$ 110.00	\$ 220.00
13	REAR END PANEL	1	\$ 680.00	\$ 680.00
14	REAR END PANEL TOP GARNISH	1	\$ 422.60	\$ 422.60

TOTAL PRICE \$ 5,763.00

LESS 25% \$ 1,440.75

SUB TOTAL PRICE \$ 4,322.25

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00

2	REAR BOOTLID OUTER GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
3	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
4	REAR END PANEL TOP GARNISH CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
5	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
6	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	<i>new</i>
TOTAL			\$	430.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,000.00	\$ 1,000.00	<i>2w</i>
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00	<i>2w</i>
3	TUFF COAT	1	\$ 200.00	\$ 200.00	<i>+</i>
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	<i>+</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00	<i>+</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	<i>50</i>
7	TRANSFER BOOTLID MECHANISM	1	\$ 120.00	\$ 120.00	<i>+</i>

TOTAL \$ 2,780.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	4,752.25
TOTAL LABOUR COST	\$	2,780.00
TOTAL REPAIR COST	\$	7,532.25

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adrian Lj
4/5 02/12/24

03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: