



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMR 9729Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$520.00	\$0.00
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	\$90.00	\$0.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	\$440.00	\$0.00
	LESS 25.00% DISCOUNT		(\$262.50)	\$0.00
			\$787.50	\$0.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	REAR BUMPER CLIP (SN)	NOT NECESSARY	\$100.00	\$0.00
			\$100.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO TUFF COATING ON AFFECTED AREAS	NOT NECESSARY	\$150.00	\$0.00
	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER RH.		\$500.00	\$300.00
	TO SPRAY PAINTING ON AFFECTED AREA		\$500.00	\$400.00
			\$1,150.00	\$700.00
GRAND TOTAL			\$2,037.50	\$700.00
RECOMMENDED COST OF REPAIRS				\$700.00
Report Ref No: CS/FCI24060288/Rvh3e2				

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS