

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	26/11/2024
CLAIM TYPE:	T/P CLAIM
TO:	CHINA TAIPING
VEHICLE DETAILS	
VEHICLE NO:	GBJ2258J
MAKE & MODEL:	TOYOTA DYNA 150 5MT
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	18 November, 2024
TIME:	0620HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,688.20	\$ 1,688.20
2	TAILGATE HINGE <i>2 pieces Bent</i>	4	\$ 155.30	\$ 621.20
3	TAILGATE SIDE LOCK <i>Dented</i>	1	\$ 290.00	\$ 290.00
4	TAILGATE STOPPER <i>Misalign</i>	1	\$ 68.20	\$ 68.20
5	TAILGATE STOPPER BRACKET <i>Bent</i>	1	\$ 198.50	\$ 198.50
6	TAILLAMP <i>LH cracked</i>	1	\$ 280.00	\$ 280.00
7	TAILLAMP BRACKET <i>Bent LH</i>	1	\$ 170.00	\$ 170.00
8	END PANEL <i>Dented</i>	1	\$ 820.60	\$ 820.60

TOTAL PRICE \$ 4,136.70

LESS 25% \$ 1,034.18

SUB TOTAL PRICE \$ 3,102.53

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	REAR NUMBER PLATE HOLDER <i>Bent</i>	1	\$ 150.00	\$ 150.00
3	TAILGATE 70KM/H <i>3 pcs</i>	1	\$ 30.00	\$ 30.00
4	TAILGATE 13 PAX <i>3 pcs</i>	1	\$ 30.00	\$ 30.00
5	TAILGATE TOYOTA STICKER <i>3 pcs</i>	1	\$ 30.00	\$ 30.00
6	TAILGATE DYNA STICKER	1	\$ 55.00	\$ 55.00
7	REVERSE SENSOR <i>Dented</i>	1	\$ 200.00	\$ 200.00

8	REVERSE SENSOR BRACKET <i>rw</i>	1	\$ 150.00	\$ 150.00	<i>30</i>
9	STEP BRACKET <i>Bent</i>	1	\$ 250.00	\$ 250.00	<i>150</i>
			TOTAL	\$ 945.00	

560

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,200.00	\$ 1,200.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,200.00	\$ 1,200.00	<i>800</i>
3	TUFF COAT	1	\$ 200.00	\$ 200.00	<i>60</i>
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	<i>30</i>
5	REMOVE AND REFIX TAILGATE ALUMINIUM	1	\$ 150.00	\$ 150.00	<i>+</i>
6	REMOVE AND REFIX SIDE GATE ALUMINIUM	1	\$ 150.00	\$ 150.00	<i>+</i>
7	REMOVE AND REFIX REAR EXHAUST PIPE	1	\$ 150.00	\$ 150.00	<i>+</i>
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	<i>50</i>

1540

TOTAL \$ 3,230.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	4,047.53
TOTAL LABOUR COST	\$	3,230.00
TOTAL REPAIR COST	\$	7,277.53

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
L/S 26/11/24.

06 Days

Labour: 4725.37

L/S 3750