

ASS. REC. BY:

REF: F021 CS/FCI24110443/Kvp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s BIFG

of _____

Insured: SHA 9470S

Policy No. _____

Claims No. D24010133MFCT

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 23k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK85P38A Yr Regn: 01, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Altis c.c. 1598Colour: M. Silver A/C: Insured / Std / Nil / NASp. Reading: 35050 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NR053REH104540842Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 3 mm R/Bal. 4 mmL/Bal. 3 mm L/Bal. 4 mmD.O.A. 18/11/24 D.O.I. 21/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11/24 71P4 84700L Car (red 12,371.14, 72%)

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 416D

Vehicle Details

Vehicle No.: SKZ5838A
Vehicle to be Exported: Yes
Intended Deregistration Date: 19 Nov 2024
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: 1ZRY222440
Chassis No.: MR053REH104540842
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$17,804.00
Original Registration Date: 27 Jan 2016
First Registration Date: 27 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$17,804.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jan 2026
PARF Rebate Amount: \$9,792.00

Intended COE Rebate Details

COE Expiry Date: 26 Jan 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$45,002.00
COE Rebate Amount: \$5,334.00
Total Rebate Amount: \$15,126.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 19 Nov 2024

OK



Sin Ming Autocare BFG Pte Ltd

176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 | Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

MS First Capital Insurance Ltd
16 Raffles Quay
#42-01, Hong Leong Building
Singapore 048581

Attn: Motor Claim Dept

CHASSIS : MR053REH104540842

Not Withheld
1/Rp \$4700
Repair After Pains
ESTIMATE

6 days

VEHICLE NO: **SKZ5838A**
MAKE/MODEL: **TOYOTA ALTIS**
DOA: **18.11.24**

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:				
1	BOOT LID	1	830.50	830.50 ✓
2	BOOT LID WEATHERSTRIP	101-755W1	203.50	203.50 509.50
3	BOOT LOCK	1	420.20	420.20 ✓
4	BOOT EMBLEM LOGO	1	66.00	66.00 ✓
5	BOOT EMBLEM COROLLA	1	60.61	60.61 ✓
6	BOOT EMBLEM ALTIS	1	67.54	67.54 ✓
7	TAIL LAMP RH	1	434.50	434.50 ✓
8	TAIL LAMP LH	1	434.50	434.50 ✓
9	REAR END PANEL	1	649.00	649.00 ✓
10	REAR FENDER LH	1	1,798.61	1,798.61 X
11	REAR FENDER RH	1	1,798.61	1,798.61 X
12	REAR BUMPER	1	870.98	870.98 ✓
13	REAR BUMPER BRACKET LH	1	100.87	100.87 ✓
14	REAR BUMPER BRACKET RH	1	100.87	100.87 ✓
15	REAR BUMPER SIDE RETAINER LH	1	132.00	132.00 ✓
16	REAR BUMPER SIDE RETAINER RH	1	132.00	132.00 ✓
17	REAR BUMPER REFLECTOR RH	1	89.21	89.21 X
18	REAR BUMPER REFLECTOR LH	1	89.21	89.21 X
19	REAR BOOT LID REFLECTOR LH	1	372.90	372.90 X
20	REAR BOOT LID REFLECTOR RH	1	372.90	372.90 X
21	REAR BOOT LID CHROME	1	410.08	410.08 X
22	REAR BOOT LID INNER TRIM	1	538.67	538.67 X
23	REAR FENDER INNER TRIM RH	1	548.68	548.68 X
24	REAR FENDER INNER TRIM LH	1	548.68	548.68 X
25	REAR END PANEL TOP GARNISH	1	264.00	264.00 ✓
26	REAR COMPARTMENT	1	832.70	832.70 X
27	REAR BOOT LID HINGE RH	1	103.29	103.29 X
28	REAR BOOT LID HINGE LH	1	103.29	103.29 X
29	REAR TAIL LAMP PANEL LH	1	164.89	164.89 X
30	REAR TAIL LAMP PANEL RH	1	164.89	164.89 X
31	REAR NUMBER PLATE LAMP RH	1	77.88	77.88 X
32	REAR NUMBER PLATE LAMP LH	1	77.88	77.88 X
33	REAR BUMPER REINFORCEMENT	1	434.50	434.50 ✓

34	REAR FENDER INNER SHIELD LH	1	275.00	Sh	275.00	X
35	REAR TAIL LAMP CLIP RH	1	20.00	na	20.00	✓
36	REAR TAIL LAMP CLIP LH	1	20.00	na	20.00	✓
37	REAR COMPARTMENT COVER	1	293.70	CM	293.70	✓
38	REAR GLASS MOULDING	1	78.50	na	78.50	X
		Sub Total (S\$) :		13,981.14		
		Discount (0%) :		-		
		Total Parts (S\$) :		13,981.14		

SPECIAL NETT ITEMS

1	REAR REVERSE SENSOR RH	1	180.00	Pd	180.00	} 2000
2	REAR REVERSE SENSOR LH	1	180.00		180.00	
3	REAR END PANEL SEALANT	1	80.00	na	80.00	3000
4	REAR NUMBER PLATE	1	50.00	Sh	50.00	X
5	REAR NUMBER PLATE HOLDER	1	30.00	Sh	30.00	X
6	REAR REVERSE CAMERA	1	380.00	Sh	380.00	X
7	REAR GLASS SEALANT	1	50.00	na	50.00	X
		Sub Total (S\$) :		950.00		

LABOUR:

1	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY	1,200.00	800
2	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON AFFECTED PORTION	1,200.00	800
3	TO APPLY RUST PROOFING ON REPAIRED,REPLACE PANEL	180.00	600
4	TO REMOVE/REFIT REAR CUSHION SEAT,SPEAKER BOARD,ROOF UPHOLSTERY TO FACILITATE REPAIRS	280.00	600
5	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	150.00	X
6	TO CHECK WIRING FUNCTIONS	80.00	200
Total Labour (S\$) :		3,090.00	

Total Amount (S\$) : 17,071.14


for Sin Ming Autocare BFG Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: