12/11/24, 8:41 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24110444/KVP3M4

HR16974123B

193918 km

MNTBBAB17Z0024844

Date: 11/12/2024

REFERENCE

Handling Insurer: EC

ECICS Limited

Policy No:

Claimant Vehicle No :

SKW4268S

Insured Vehicle No:

SNF7845K

Date of Loss:

17/11/2024

Nature of Claim:

TP

Claim No: D

DMPC2401600H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKW4268S

Make & Model:

NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG

2WD 4DR (A)

Reg. Date:

29/10/2015 (Man. Year: 2015)

Metallic Grey

N/A

Colour: M

Engine Capacity: Market Value/New Car 1598 сс

Price:

Sum Insured (S\$):

Market Value/New Car Price

Yes

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

serviceable):

Yes

Engine Modification: No Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 205/55R16 LAUFENN 4 mm LAUFENN 4 mm

Rear Left Side: Rear Right Side:

Rear Tyre Size:

205/55R16 Hankook 3 mm

Hankook 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,289.46	1,840.10	2,449.36	57.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,810.00	1,120.00	1,690.00	60.14
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,099.46	2,960.10	4,139.36	58.31
	Approved Total (Overridden) (S\$)		2,350.00		
	Nett Amount (S\$)	7,099.46	2,350.00	4,749.46	66.90

INSPECTION

Date of Assignment:

21/11/2024

AUBURN AUTO PTE LTD

Date Inspected:

26/11/2024 Inspected At:

BLOCK 1 SIN MING IND ESTATE SECTOR C

#01-135 SINGAPORE 575636

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2024)	
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	: (Unsubmitted, no print-code for SKW4268S)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,447.00 FL	*759.00 FL
2	1		*FRONT BUMPER GRILLE LEFT	Serviceable	302.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT BRACKET LEFT	Repair	174.00 FL	*-FL
4	1		*FRONT SUPPORT PANEL	Repair	991.40 FL	*-FL
5	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	375.00 FL	*- FL
6	1		*HEADLAMP	Cut	1,180.00 FL	*1,180.00 FL
7	2		*HEADLAMP LOWER BRACKET	Serviceable	130.00 FL	*- FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
9	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*-FS
10	1		*SET FRONT NUMBER PLATE	Dented	50.00 FS	*45.00 FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	Sub Total (S\$)	4,749.40	2,034.00
			- List Item Discount on L Item	· · · · · · · · · · · · · · · · · · ·	459.94	193.90
				Total Parts (S\$)	4,289.46	1,840.10
			Report was unsubmitted during this pr	int-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REFIT & INSTALL ALL ACCIDENT AFF. PORTIONS	New	120.00	0.00
2	TO REMOVE & REFIX AIRCON ASSY, VACUUM AND TOP UP GAS	New	120.00	0.00
3	TO CHECK ALL NECESSARY WIRING }	New	100.00	20.00
4	TO REMOVE & REFIT HEADLIGHT ASSY }	New	120.00	0.00
5	TO PANEL BEAT ON AFF. PORTIONS	New	1,000.00	500.00
6	TO PUTTY & RESPRAY ALL ACCIDENT AFF. PORTIONS	New	1,200.00	600.00
7	TO APPLY COATING ON ALL ACCIDENT AFF. PORTIONS	New	150.00	0.00
	Gross Lab	our Cost (S\$)	2,810.00	1,120.00
	Report was unsubmitted during the	nis print-out.		

< END OF ESTIMATES >