



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110446/Uqp3e2
16 RAFFLES QUAY	Date:	11/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3268U	Veh. Inspected	GBF 3907J
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24010201MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	21/11/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2982
Engine No.	1KD2632899	Year of Reg.	30/09/2016
Chassis No.	JTFAT35Y20K206721	Colour	SILVER
Odometer	232985 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	FALKEN	6
L/H Front Tyre	195R15	FALKEN	6
R/H Rear Tyre	155R12 (D)	FALKEN	6/6
L/H Rear Tyre	155R12 (D)	FALKEN	6/6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/11/2024	Inspection Date	22/11/2024
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		

5a. Remarks
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days