

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 15.11.2024

TO	:	AIG MOTOR CLAIMS DEPTS
VEHICLE NO	:	SMX8785K
MODEL	:	BMW 116i
DATE OF ACCIDENT	:	15.11.2024
TIME OF ACCIDENT	:	09:10 HOURS

Daphne.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delnd</i>	1	\$ 1,690.80	\$ 1,690.80
2	FRONT BUMPER LOGO <i>per</i>	1	\$ 59.85	\$ 59.85
3	FRONT BUMPER TOWING COVER <i>New</i>	1	\$ 108.60	\$ 108.60
4	FRONT BUMPER REINFORCEMENT <i>New</i>	1	\$ 726.70	\$ 726.70
5	FRONT BUMPER SIDE BOTTOM COVER GARNISH RH <i>New</i>	1	\$ 276.65	\$ 276.65
6	FRONT BUMPER UPPER GRILLE <i>New</i>	1	\$ 331.30	\$ 331.30
7	FRONT BUMPER UPPER GRILLE CHROME <i>New</i>	1	\$ 421.00	\$ 421.00
8	FRONT GRILLE INNER COVER GARNISH <i>New</i>	1	\$ 128.60	\$ 128.60
9	FRONT BUMPER LOWER GRILLE <i>New</i>	1	\$ 218.60	\$ 218.60
10	FRONT BUMPER SIDE GRILLE INNER GARNISH RH	1	\$ 148.10	\$ 148.10
11	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 254.55	\$ 254.55
12	FRONT BUMPER LOWER BEAM <i>New</i>	1	\$ 197.35	\$ 197.35
13	FRONT BUMPER SIDE AIR VENT RH <i>damaged</i>	1	\$ 168.00	\$ 168.00
14	FRONT BUMPER SIDE AIR DUCT RH <i>damaged</i>	1	\$ 183.00	\$ 471.40
15	FRONT BUMPER FOGLAMP COVER GARNISH RH <i>New</i>	1	\$ 116.45	\$ 116.45
16	FRONT BUMPER SENSOR <i>1 piece damaged</i>	3	\$ 215.60	\$ 646.80
17	FRONT BUMPER SENSOR HOLDER <i>1 piece New</i>	6	\$ 75.00	\$ 450.00
18	FRONT BUMPER TEMPERATURE SENSOR <i>New</i>	1	\$ 235.00	\$ 235.00
19	HEADLAMP <i>Cut RH</i>	2	\$ 3,485.20	\$ 6,970.40
20	HEADLAMP TOP RUBBER RH <i>New</i>	1	\$ 27.40	\$ 27.40
21	HEADLAMP LOWER BRACKET RH <i>New</i>	2	\$ 114.80	\$ 229.60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMX8785K**
 MODEL : **BMW 116i**
 DATE OF ACCIDENT : 15.11.2024
 TIME OF ACCIDENT : 09:10 HOURS

22	HEADLAMP LOWER GARNISH RH <i>from</i>	1	\$ 117.95	\$ 117.95
23	HEADLAMP TOP COVER GARNISH <i>new</i>	2	\$ 196.70	\$ 393.40
24	FRONT SUPPORT PANEL <i>new</i>	1	\$ 864.20	\$ 864.20
25	FRONT FENDER INNER COWLING RH <i>Dehnd</i>	1	\$ 366.90	\$ 366.90

6678345
6446.172

TOTAL PRICE \$ 15,619.60
 LESS 5% \$ 780.98
SUB TOTAL PRICE \$ 14,838.62

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER SIDE BOTTOM COVER GARNISH RH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	COOLANT <i>new</i>	1	\$ 180.00	\$ 180.00

TOTAL \$ 310.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	<i>300</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>200</i>
3	TUFF COAT	\$ 250.00	<i>X</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REMOVE AND REFIX AIRCON CONDENSER	\$ 120.00	<i>X</i>
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>X</i>
7	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>X</i>
8	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMX8785K**
MODEL : **BMW 116i**
DATE OF ACCIDENT : 15.11.2024
TIME OF ACCIDENT : 09:10 HOURS

9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 850.00	150
---	--	-----------	-----

TOTAL \$4,110.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,148.62
TOTAL LABOUR COST : \$ 4,110.00
TOTAL REPAIR COST : \$ 19,258.62

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP :8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 15/11/24.

03 Days

total 17256.17

L/S: 58K ✓

730