

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0876/2024/KS
DATE : 22-Nov-24
WIP : 39285

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS TAN WANG CHEOW
ADDRESS : 53 JALAN SENANG
SINGAPORE 418345

TELEPHONE : HP +65 96188660
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800129508-06
VEHICLE NO : **SMG 9900 C**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 31/10/2018
ENGINE NO : CVK 067574
CHASSIS NO : WAUZZZF5XJA129733
MILEAGE : 51,492 KM
DATE IN : 20-Nov-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Nov-24
PLACE OF ACCIDENT : NEAR 329 UBI AVE 1, SINGAPORE 400329
PIE (AIRPORT) SLIP ROAD JALAN EUNOS LP43656

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 9900 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	/
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 780.00	480
3	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,600.00	?
4	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC.	S/N \$ 1,600.00	?
5	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING. TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	\$ 13,000.00	2750
6	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS SILL PANEL, LHS REAR DOOR, DOOR ENTRANCE, SPARE WHEEL HOUSING, DRAIN PANEL, ROOF CHANNEL AND END PANELLING.	\$ 11,000.00	2750
SUBTOTAL LABOUR CHARGES		: \$ 28,340.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 9900 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	/
8	TO CARRY OUT WATER SEEPAGE TEST FOR AFFECTED GLASSES.	S/N \$	280.00	/
9	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	/
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$ 29,792.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 9900 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>de ✓</i>	1	\$ 3,397.00	
2	REAR BUMPER FIXING PARTS <i>X</i>	1	\$ 292.00	
3	REAR BUMPER SECURING STRIP <i>re ✓</i>	1	\$ 280.00	
4	REAR BUMPER CHROME TRIM <i>can ✓</i>	1	\$ 1,267.00	
5	REAR LIGHT REFLECTOR - LH <i>?</i>	1	\$ 49.00	
6	LED TAIL LIGHT - LH OUTER <i>sc ✓</i>	1	\$ 1,427.00	
7	LED TAIL LIGHT TRIM - LH OUTER <i>sc ✓</i>	1	\$ 41.00	
8	LED TAIL LIGHT - LH INNER <i>mis ✓</i>	1	\$ 1,276.00	
9	LED TAIL LIGHT TRIM - LH INNER <i>mis ✓</i>	1	\$ 41.00	
10	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 1,297.00	
11	REAR BUMPER REINFORCEMENT BEAM SEAL <i>?</i>	2	\$ 36.00	
12	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 56.00	
13	REAR BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$ 58.00	
14	REAR BUMPER GUIDE SECTION PIN - LH / RH <i>?</i>	2	\$ 7.00	
15	REAR PARKING AID SENSOR <i>dis ✓</i>	1 <i>✓</i>	\$ 572.00	
16	REAR PARKING AID SENSOR SEAL RING <i>re ✓</i>	4	\$ 11.00	
17	REAR BUMPER WIRING SET <i>?</i>	1	\$ 796.00	
18	REAR LID OPENING CONTROL UNIT <i>?</i>	1	\$ 617.00	
19	REAR LID OPENING CONTROL UNIT RETAINER <i>?</i>	1	\$ 10.00	
20	REAR LID OPENING SENSOR LINE <i>?</i>	1	\$ 244.00	
SUB TOTAL SPARE PARTS		:	\$ 11,774.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 9900 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AERIAL FOR ACESS AND START AUTHORISATION ?	1	\$ 129.00	
22	AERIAL RETAINER ?	1	\$ 32.00	
23	TELEPHONE AERIAL ?	1	\$ 207.00	
24	REAR LID <i>bt</i> ✓	1	\$ 4,586.00	
25	AUDI EMBLEM <i>m</i> ✓	1	\$ 183.00	
26	"A5" EMBLEM <i>m</i> ✓	1	\$ 116.00	
27	"TFSI" EMBLEM <i>m</i> ✓	1	\$ 116.00	
28	REAR LID HINGE - LH / RH ?	2	\$ 568.00	
29	REAR LID ATTACHMENT PARTS X	1	\$ 171.00	
30	REAR LID WEATHER STRIP <i>de</i> ✓	1	\$ 294.00	
31	REAR LID PACKING ADHESIVE <i>m</i> ✓	1	\$ 23.00	
32	REAR FENDER - LH <i>regr</i> ✓	1	\$ 5,180.00	
33	REAR QUARTER GLASS - LH X	1	\$ 896.00	
34	PRIMER X	2	\$ 54.00	
35	REAR WINDSCREEN <i>regr</i> ✓	1	\$ 1,463.00	
36	THIRD BRAKE LIGHT <i>m</i> ✓	1	\$ 782.00	
37	REAR WHEEL HOUSING LINER- LH X	1	\$ 332.00	
38	REAR WHEEL HOUSING LINER ATTACHMENT PARTS X	1	\$ 153.00	
39	SIDE MEMBER TRIM ATTACHMENT PARTS - LH X	1	\$ 153.00	
40	SIDE MEMBER TRIM ADHESIVE TAPES - LH X	1	\$ 233.00	
SUB TOTAL SPARE PARTS		:	\$ 15,671.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 9900 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REAR CROSS PANEL <i>bt</i> ✓	1	\$	414.00	
42	REAR CROSS PANEL REINFORCEMENT BEAM <i>bt</i> ✓	1	\$	730.00	
43	ACRYLIC SEALANT <i>m</i> ✓	S/N	\$	180.00	
44	CAVITY WAX <i>m</i> ✓	S/N	\$	140.00	
45	STONE CHIP <i>m</i> ✓	S/N	\$	180.00	
46	1/4 GLASS SEALANT <i>X</i>	S/N	\$	100.00	
47	METAL FILLER POWDER <i>m</i> ✓	S/N	\$	280.00	
48	REAR NO PLATE <i>X</i>	S/N	\$	60.00	
49	REAR WINDSCREEN SEALANT <i>m</i> ✓	S/N	\$	200.00	
50	SUNDRIES <i>?</i>		\$	800.00	
TOTAL SPARE PARTS		:	\$	30,529.00	
TOTAL LABOUR CHARGES		:	\$	29,792.00	
GRAND TOTAL		:	\$	60,321.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *RASUL - Hp 900 10068*
 SURVEYED DATE : *22/11/24*
 AUTHORISED DATE :
 EXCESS COST : *8 days*
 LIABILITY : *EXCESS: TBA*
 REMARKS : *Revert
Des & f paint*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT