



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0876/2024/KS
DATE : 22-Nov-24
WIP : 39285

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Rasul,

8 Days + 1 Sun - OK - Allan Boo

20-Jan-25

OWNER'S NAME : MS TAN WANG CHEOW
ADDRESS : 53 JALAN SENANG
SINGAPORE 418345

TELEPHONE : HP +65 96188660
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800129508-06
VEHICLE NO : **SMG 9900 C**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 31/10/2018
ENGINE NO : CVK 067574
CHASSIS NO : WAUZZZF5XJA129733
MILEAGE : 51,492 KM
DATE IN : 20-Nov-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Nov-24
PLACE OF ACCIDENT : NEAR 329 UBI AVE 1, SINGAPORE 400329
PIE (AIRPORT) SLIP ROAD JALAN EUNOS LP43656

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 9900 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	780.00	\$	480.00
3	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,600.00	\$	1,600.00
4	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC.	S/N \$	1,600.00		
5	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING. TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	\$	13,000.00	\$	2,750.00
6	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS SILL PANEL, LHS REAR DOOR, DOOR ENTRANCE, SPARE WHEEL HOUSING, DRAIN PANEL, ROOF CHANNEL AND END PANELLING.	\$	11,000.00	\$	2,750.00
SUBTOTAL LABOUR CHARGES		:	\$ 28,340.00	\$	7,940.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 9900 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
				\$ 7,940.00
7	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	\$ 400.00
8	TO CARRY OUT WATER SEEPAGE TEST FOR AFFECTED GLASSES.	S/N \$	280.00	\$ 280.00
9	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	\$ 480.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		:	\$ 29,792.00	\$ 9,392.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 9900 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,397.00	\$ 2,717.60
2	REAR BUMPER FIXING PARTS	1	\$ 292.00	
3	REAR BUMPER SECURING STRIP	1	\$ 280.00	\$ 223.60
4	REAR BUMPER CHROME TRIM	1	\$ 1,267.00	\$ 1,013.60
5	REAR LIGHT REFLECTOR - LH	1	\$ 49.00	
6	LED TAIL LIGHT - LH OUTER	1	\$ 1,427.00	
7	LED TAIL LIGHT TRIM - LH OUTER	1	\$ 41.00	\$ 32.40
8	LED TAIL LIGHT - LH INNER	1	\$ 1,276.00	\$ 1,020.80
9	LED TAIL LIGHT TRIM - LH INNER	1	\$ 41.00	\$ 32.40
10	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,297.00	\$ 1,037.60
11	REAR BUMPER REINFORCEMENT BEAM SEAL	2	\$ 36.00	\$ 28.80
12	REAR BUMPER GUIDE SECTION - LH	1	\$ 56.00	
13	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 58.00	\$ 45.44
14	REAR BUMPER GUIDE SECTION PIN - LH / RH	2	\$ 7.00	
15	REAR PARKING AID SENSOR	2	\$ 572.00	\$ 228.80
16	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	
17	REAR BUMPER WIRING SET	1	\$ 796.00	
18	REAR LID OPENING CONTROL UNIT	1	\$ 617.00	
19	REAR LID OPENING CONTROL UNIT RETAINER	1	\$ 10.00	
20	REAR LID OPENING SENSOR LINE	1	\$ 244.00	
SUB TOTAL SPARE PARTS		:	\$ 11,774.00	\$ 6,381.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 9900 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 6,381.04
21	AERIAL FOR ACESS AND START AUTHORISATION	1	\$ 129.00	
22	AERIAL RETAINER	1	\$ 32.00	
23	TELEPHONE AERIAL	1	\$ 207.00	
24	REAR LID	1	\$ 4,586.00	\$ 3,668.80
25	AUDI EMBLEM	1	\$ 183.00	\$ 146.00
26	"A5" EMBLEM	1	\$ 116.00	\$ 92.80
27	"TFSI" EMBLEM	1	\$ 116.00	\$ 92.80
28	REAR LID HINGE - LH / RH	2	\$ 568.00	
29	REAR LID ATTACHMENT PARTS	1	\$ 171.00	
30	REAR LID WEATHER STRIP	1	\$ 294.00	\$ 234.80
31	REAR LID PACKING ADHESIVE	1	\$ 23.00	\$ 18.32
32	REAR FENDER - LH	1	\$ 5,180.00	
33	REAR QUARTER GLASS - LH	1	\$ 896.00	
34	PRIMER	2	\$ 54.00	\$ 21.68
35	REAR WINDSCREEN	1	\$ 1,463.00	\$ 1,170.40
36	THIRD BRAKE LIGHT	1	\$ 782.00	\$ 625.60
37	REAR WHEEL HOUSING LINER- LH	1	\$ 332.00	
38	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 153.00	
39	SIDE MEMBER TRIM ATTACHMENT PARTS - LH	1	\$ 153.00	
40	SIDE MEMBER TRIM ADHESIVE TAPES - LH	1	\$ 233.00	
SUB TOTAL SPARE PARTS			\$ 15,671.00	\$ 12,452.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 9900 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 12,452.24
41	REAR CROSS PANEL	1 \$	414.00 \$	331.20
42	REAR CROSS PANEL REINFORCEMENT BEAM	1 \$	730.00 \$	583.60
43	ACRYLIC SEALANT	S/N \$	180.00 \$	180.00
44	CAVITY WAX	S/N \$	140.00 \$	140.00
45	STONE CHIP	S/N \$	180.00 \$	180.00
46	1/4 GLASS SEALANT	S/N \$	100.00	
47	METAL FILLER POWDER	S/N \$	280.00 \$	280.00
48	REAR NO PLATE	S/N \$	60.00	
49	REAR WINDSCREEN SEALANT	S/N \$	200.00 \$	200.00
	ADD PARTS - SUPPLEMENTARY			\$ 2,182.00
50	SUNDRIES	\$	800.00 \$	6.72
TOTAL SPARE PARTS		:	\$ 30,529.00	\$ 16,535.76
TOTAL LABOUR CHARGES		:	\$ 29,792.00	\$ 9,392.00
GRAND TOTAL		:	\$ 60,321.00	\$ 25,927.76

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0876/2024/KS
Date 27-Nov-24
Service Advisor GLORY
Pages 1 of 1
Regn No SMG 9900 C
Model No AUDI A5 SPORTBACK 2.0 TFS

Quantity	Description	Unit Price	Amount
Labours			
1	TRIM FOR REAR END PANELLING.	\$ 441.00	\$ 352.40
2	REAR LID ABSORBER LHS	\$ 2,287.00	\$ 1,829.60
GRAND TOTAL		\$ 2,728.00	\$ 2,182.00

For Premium Automobiles Pte Ltd

Authorised Signature