



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060289/Avh3
(BUDGET DIRECT INSURANCE)	Date:	16/08/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 6196D	Veh. Inspected	SGM 159A
Policy No.	-	Coverage	0
Claim No.	C10030181/CH	Excess	\$0.00
Assign From	MICHAEL	Assign Date	27/06/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER	C.C	1998
Engine No.	8ARZ135425	Year of Reg.	30/08/2019
Chassis No.	JTEZB3GH90J002916	Colour	BLUE
Odometer	89555 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55 R18	FARROAD	6
L/H Front Tyre	235/55 R18	FARROAD	6
R/H Rear Tyre	235/55 R18	FARROAD	6
L/H Rear Tyre	235/55 R18	FARROAD	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/06/2024	Inspection Date	28/06/2024
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days