



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 28/06/2022

Attn: The Motor Claims Department

Your Insured Vehicle - SLK 6196 D

Auto & General Insurance (Singapore) Pte Ltd

190 Clemenceau Ave #03-01 Singapore Shopping Centre

Singapore 239924

Tel: 62212199

Email: Claims@budgetdirect.com.sg

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WITHOUT PREJUDICE

Dear Sir / Madam

Accident Involved Vehicle Toyota Harrierd SGM159A And SLK6196D on 26/06/2024 at 08:10

To supply;

1pc	Rear Boot Cover	Dented		\$	2,126.40	✓
1pc	Rear Boot Cover Rubber	new		\$	442.00	✓
1pc	Rear Boot Cover Inner Lock	new		\$	628.20	✓ 495
1pc	Rear Boot Cover Harrier Plate	new		\$	82.60	✓
1pc	Rear Boot Cover Turbo Plate	new		\$	98.80	✓
1pc	Rear Boot Cover Logo	new		\$	77.20	✓
1pc	Rear Panel	Dented	5702.80	\$	1,006.40	✓ 379
1pc	Rear panel Inner Garnish	new		\$	445.00	✓
1pc	Rear Bumper	Dented	4277.10	\$	904.00	✓
1pc	Rear Bumper Sponge	new		\$	122.60	✓
1pc	Rear Bumper Side Retainer	new	\$82.70 x 4pcs	\$	330.80	✓
1pc	Rear Bumper Lower Spoiler	Dented		\$	488.00	✓
1pc	Rear Bumper Reflectors	new	\$57.60 x 2pcs	\$	115.20	✓
				\$	6,867.20	
				\$	1,716.80	
				\$	5,150.40	

4pcs	Reverse Sensors	new	\$481.90 x 4pcs	\$	1,927.60	S/Nett ✓
2pcs	Rear Boot Cover Windscreen Moulding	new	\$57.70 x 2pcs	\$	115.40	S/Nett ✓
1pc	Rear Boot Cover Windscreen Glass Seal	new	\$29.30 x 2pcs	\$	58.60	S/Nett ✓
1pc	Rear Windscreen Sealant	new		\$	60.00	S/Nett ✓
1pc	Rear Number Plate	new		\$	45.00	S/Nett ✓

To dismantl & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affected portion.

To remove and refix rear windscreen

To remove reverse sensor.

To check wiring functions.

Supplementary: 1007.25

total: 6716335

4/5: 57K

\$	900.00	✓
\$	950.00	✓
\$	180.00	120
\$	150.00	50
\$	80.00	30
\$	14,767.40	

As per
1/5 28/06/24
No of days: 206 Days



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 28/06/2022

Attn: The Motor Claims Department

Your Insured Vehicle - SLK 6196 D

Auto & General Insurance (Singapore) Pte Ltd

190 Clemenceau Ave #03-01 Singapore Shopping Centre

Singapore 239924

Tel: 62212199

Email: Claims@budgetdirect.com.sg

WITHOUT PREJUDICE

Dear Sir / Madam

Supplimentary item Vehicle Toyota Harrierd SGM159A And SLK6196D on 26/06/2024 at 08:10

To supply;

1pc Damper, Rear Suspension Tower

Bent

\$

1,734.00

1343

1343

Supplementary: 1007.25