

ASSIGNMENT

Front: _____ Date: _____
 Estin: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To In Vehicle No: _____
 at W/O m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGM159A Yr Regn: 2019 August
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Harrier C.D. 1998
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 89555 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTEZB3GH90J002916
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/55R18
 R: 235/55R18

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>28/06/24</u>

Survey held at Kai Motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Direct</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>Yes</u> <u>No</u>
	<u>MV</u>
	<u>PV</u>
	<u>Nett</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Report Format: _____

Report Form: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. \$1 _____

Photos _____

Others _____



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 28/06/2022

Attn: The Motor Claims Department

Your Insured Vehicle - SLK 6196 D

Auto & General Insurance (Singapore) Pte Ltd

190 Clemenceau Ave #03-01 Singapore Shopping Centre

Singapore 239924

Tel: 62212199

Email: Claims@budgetdirect.com.sg

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WITHOUT PREJUDICE

Dear Sir / Madam

Accident Involved Vehicle Toyota Harrierd SGM159A And SLK6196D on 26/06/2024 at 08:10

To supply;

1pc	Rear Boot Cover	Dented		\$	2,126.40	✓
1pc	Rear Boot Cover Rubber	new		\$	442.00	✓
1pc	Rear Boot Cover Inner Lock	new		\$	628.20	✓ 495
1pc	Rear Boot Cover Harrier Plate	new		\$	82.60	✓
1pc	Rear Boot Cover Turbo Plate	new		\$	98.80	✓
1pc	Rear Boot Cover Logo	new		\$	77.20	✓
1pc	Rear Panel	Dented		\$	1,006.40	✓
1pc	Rear panel Inner Garnish	new		\$	445.00	✓
1pc	Rear Bumper	Dented		\$	904.00	✓
1pc	Rear Bumper Sponge	Cracked		\$	122.60	✓
1pc	Rear Bumper Side Retainer	new	\$82.70 x 4pcs	\$	330.80	✓
1pc	Rear Bumper Lower Spoiler	Dented		\$	488.00	✓
1pc	Rear Bumper Reflectors	new	\$57.60 x 2pcs	\$	115.20	✓
				\$	6,867.20	
Less 25%				-\$	1,716.80	
				\$	5,150.40	
						280 560!
4pcs	Reverse Sensors	2 new 2 old	\$481.90 x 4pcs	\$	1,927.60	S/Nett ✓
2pcs	Rear Boot Cover Windscreen Moulding	new	\$57.70 x 2pcs	\$	115.40	S/Nett ✓
1pc	Rear Boot Cover Windscreen Glass Seal	new	\$29.30 x 2pcs	\$	58.60	S/Nett ✓
1pc	Rear Windscreen Sealant	new		\$	60.00	S/Nett ✓
1pc	Rear Number Plate	Dented		\$	45.00	S/Nett ✓

To dismanlte & replace damage parts,panel beat where necessary

To putty,apply primer & spray paint on the affecte portion.

To remvoe and refix rear windscreen

To remove reverse sensor.

To check wiring functions.

\$ 900.00
\$ 950.00
\$ 180.00
\$ 150.00
\$ 80.00
\$ **14,767.40**

Adm
1/5 28/06/24
No of days: 206 Days