

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
GST:52832105J RCB NO:201327339E

not Authorized
recd
22/11/24
p/p 1085
2 days.

M/S : India International Insurance Pte Ltd

64 Cecil Street

#04/ #05/ #06-02

IOB Building Singapore 049711

TEL: 6347 6100

FAX: 6224 4174 / 6225

ATTN: Motor Claim Department

Estimate No: ES1602322

Date: 08 Nov 2024

Policy No: 2024-v5022802-vecv

Veh Reg No: GBF680G

Make/Model: TOYOTA DYNA 3.0
MANUAL

Chassis No: KDY2318023932

Engine No: 1KD2598476

Reg. Date: 08/06/2016

Your Ref No: WEE GUAN ENG PL

Claim Type: Third Party

Accident Date: 08/11/2024

TP Veh Reg No: GBD807U

Estimate Repair Cost to Vehicle No :GBF680G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 Rear Tipper Door Tailgate	2,100.00	1 PC	R 2,100.00 X	
2 Rear Tipper Rubber Stopper -LH	100.00	1 PC	Turn 100.00 ✓ 60 S/N	
3 Rear Tipper Rubber Stopper Bracket -LH	1,800.00	1 PC	R 1,800.00 X	
4 Rear Tipper Lock	180.00	1 PC	R 180.00 X	
5 Rear Tipper Hinge	230.00	1 PC	17 230.00 X	
6 Rear Tipper Side Frame	950.00	1 SET	17 950.00 X	
7 Tail Lamp Assy -LH	190.00	1 PC	one 190.00 — S/N	
8 Tail Lamp Bracket -LH	250.00	1 PC	R 250.00 X	
9 Sticker " 70 km/h "	40.00	1 PC	new 40.00 10 S/N	
10 Sticker " Tailgate "	95.00	1 PC	new 95.00 — S/N	
11 Sticker " 8" Pax "	40.00	1 PC	new 40.00 10 S/N	
			5,975.00	5,975.00
Labour				
12 Labour to renew & refit all above parts .	1,000.00	1 -	1,000.00 300	
13 Labour to check & connect & rewire & renew tail lamp .	180.00	1 -	180.00 20	
14 To rust proofing at accident affected area .	380.00	1 -	17 380.00 X	
15 To spray & painting at accident affected area .	950.00	1 -	950.00 400	
			2,510.00	2,510.00
Total				S\$ 8,485.00
Add GST @ 9%				763.65
Total Amount Payable				S\$ 9,248.65

TOTAL: SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED FORTY EIGHT AND CENTS SIXTY FIVE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For HUP LIAN HUAT ENGINEERING
WORKS

AUTHORISED SIGNATURE

S.N - 365
L - 720
1085