

ESTIMATE OF REPAIR

Veh# : **SBR90X**
 Accident Date : ~~5/11/2024~~ 4/11/2024
 Location : SIMS WAY

Model: TOYOTA VELL FIRE
 21/6/2015
 3P: FBT2649L(INCOME)


S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear tail lamp lower garnish R <i>torn</i>	372.00	✓	
2	1pc	Rear tail lamp lower garnish retainer R <i>new</i>	139.90	+	
3	1 pc	Rear bumper <i>new</i>	2,929.40	+	
4	1 set	Rear bumper clip <i>new</i>		50.00	+
5	1 pc	Rear bumper lower lid spoiler <i>new</i>		800.00	+
		Sub Total:	3,441.30	850.00	0.00
			25%	0%	10%
		After Less %:	2,580.98	850.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign accident affected area.		400.00	200
2		To spray paint on accident affected area. <i>SUN</i>		400.00	300
3		To check wiring & rewire parking sensor.		500.00	+
		Sub Total:		1,300.00	
		Total:		4,730.98	
		After less:		3,784.78	

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI,MSAE(Aust)

Adnan
 1/5 21/11/24.

02 Days.



8778 1999
 24 hr accident call



- LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 779
4/5: 600 ✓