



# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
Kaki Bukit Autohub, Singapore 417921  
Tel No. : 67461515 / 67471787 Fax No. : 67485015  
Website : www.successunited.com.sg  
Buss. Reg. No. : GST No. 200402570G

Income Insurance Limited  
Income Centre  
75 Bras Basah Road Singapore 189557

Attention : Motor Claim Department  
Contact : 6788 1777 Fax No. : 6338 1500

## Estimate : TP24-148

Date : 20/11/2024  
Vehicle Num. : CBC3138C  
Make/Model : Toyota Hiace-2016  
Chassis/Eng# : KDH2010202607/1KD2638026  
Accident Date : 05/11/2024  
Claim No. :  
Reference :  
Policy No. : SP2030537473-01

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |   |                            |  |          |
|----|---|----------------------------|--|----------|
| 1. | 1 | LIST ITEMS :               |  | 512.60   |
| 2. | 1 | Rear Lamp LH               |  | 570.60   |
| 3. | 1 | Rear Corner Panel LH       |  | 591.70   |
| 4. | 1 | Rear Bumper Assy           |  | 68.50    |
|    |   | Rear Bumper Side Holder LH |  |          |
|    |   | List TotalS\$ :            |  | 1,743.40 |
|    |   | 25.00% Discount S\$ :      |  | 435.85   |
|    |   |                            |  | 1,307.55 |

|    |   |                          |      |       |
|----|---|--------------------------|------|-------|
| 1. | 8 | SPECIAL NETT ITEMS :     | 5.71 | 45.68 |
|    |   | Rear Bumper Clips        |      | 45.68 |
|    |   | Special Nett Total S\$ : |      |       |

|  |  |                                                         |  |          |
|--|--|---------------------------------------------------------|--|----------|
|  |  | LABOUR :                                                |  | 800.00   |
|  |  | To remove, repair and replaced damaged bodyparts,       |  |          |
|  |  | realign bodyworks & where consistent to the accident    |  |          |
|  |  | To remove, rearrange electrical wirings, check lighting |  | 80.00    |
|  |  | To putty and respray painting on rear fender LH,        |  | 800.00   |
|  |  | corner panel.                                           |  |          |
|  |  | Labour Total S\$ :                                      |  | 1,680.00 |

Total S\$ : 3,033.23  
=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian C  
2/8 21/11/24  
03 Days