



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TAN KING POH

BLK 956 HOUGANG ST 91 #14-298

SINGAPORE 530956

Contact : 97221602

TP INC

VERCON

TAX INVOICE

Repair Code : CLM18263

Date in : 10/06/2024

Vehicle Num. : SFQ619E

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104105394/1ZRX039072

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID	1	949.10	+ 949.10
REAR BOOTLID '1.6' EMBLEM	1	40.10	+ 40.10
REAR BOOTLID 'ALTIS' EMBLEM	1	53.20	+ 53.20
REAR BOOTLID 'COROLLA' EMBLEM	1	53.20	+ 53.20
REAR BOOTLID 'LOGO' EMBLEM	1	66.90	+ 66.90
REAR BOOTLID HINGES L/R	2	74.40	+ 148.80
REAR BOOTLID INNER RUBBER STOPPER L/R	2	18.00	+ 36.00
REAR BOOTLID LOCK STRIKER	1	20.90	+ 20.90
REAR BOOTLID MECHANISM LOCK	1	121.10	+ 121.10
REAR BOOTLID OUTER HANDLE	1	291.50	+ 291.50
REAR BOOTLID REFLECTOR INNER BLACK GASKET RH	1	35.00	+ 35.00
REAR BOOTLID REFLECTOR INNER COVER RH	1	105.00	+ 105.00
REAR BOOTLID REFLECTOR RH	1	305.40	+ 305.40
REAR BOOTLID WEATHER STRIP	1	209.90	209.90
REAR BUMPER	1	660.80	660.80
REAR BUMPER END SEAL COVER	1	39.90	+ 39.90
REAR BUMPER REFLECTOR RH	1	46.90	46.90
REAR BUMPER SIDE BRACKET RH	1	37.60	37.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN KING POH
 BLK 956 HOUGANG ST 91 #14-298
 SINGAPORE 530956

Contact : 97221602

TAX INVOICE

Repair Code : CLM18263
 Date in : 10/06/2024
 Vehicle Num. : SFQ619E
 Model : TOYOTA COROLLA ALTIS 1.6 AUTO
 Chassis/Eng# : MR053REE104105394/1ZRX039072

REAR BUMPER SIDE RETAINER L/R	<i>New</i>	2	78.70	<i>+</i>	157.40
REAR BUMPER SPONGE	<i>Crackd</i>	1	153.80	<i>✓</i>	153.80
REAR END PANEL	<i>Dented</i>	1	727.70	<i>✓</i>	727.70
REAR END PANEL INNER TOP GARNISH	<i>New</i>	1	231.60	<i>+</i>	231.60
REAR END PANEL NOSE BRACKET RH	<i>Dented</i>	1	93.00	<i>✓</i>	93.00
REAR EXHAUST RUBBER MOUNTING	<i>New</i>	2	35.00	<i>+</i>	70.00
REAR EXHAUST SILENCER BOX	<i>New</i>	1	569.30	<i>+</i>	569.30
REAR TAILLAMP BLACK GASKET L/R	<i>New</i>	2	29.80	<i>+</i>	59.60
REAR TAILLAMP INNER PANEL RH	<i>New</i>	1	94.30	<i>+</i>	94.30
REAR TAILLAMP LOWER BRACKET RH	<i>Crackd</i>	1	71.90	<i>✓</i>	71.90
REAR TAILLAMP RH	<i>Crackd</i>	1	514.70	<i>✓</i>	514.70
Subtotal before discount					5,964.60
Percentage discount 25%					1,491.15
Sub-total 1					4,473.45
REAR BOOTLID OUTER HANDLE CLIPS - SET	<i>New</i>	1	30.00	<i>+</i>	30.00 X
REAR BUMPER CLIPS - SET	<i>New</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER REVERSE SENSOR - SET	<i>New</i>	1	250.00	<i>+</i>	250.00
REAR TAILLAMP CLIPS RH - SET	<i>New</i>	1	25.00	<i>+</i>	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN KING POH
 BLK 956 HOUGANG ST 91 #14-298
 SINGAPORE 530956

Contact : 97221602

TAX INVOICE

Repair Code : CLM18263

Date in : 10/06/2024

Vehicle Num. : SFQ619E

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104105394/1ZRX039072

Subtotal before discount	385.00
Percentage discount 0%	0.00
Sub-total 2	385.00
Parts-total	4,858.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

Labour Total	2,320.00
Parts & Labour Total	7,178.45

✓ 80.00
 30 80.00
 600 1,000.00
 800 1,000.00
 500 21/8/24
 60 80.00
 80.00

1290

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adm L
 h/s 11/06/24
 AL of d/s 05' app.

total: 2979.75
 L/s: 2.3K ✓