

ASS. REC. BY:

REF:

C721

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNE 3280Xr Regn: 031 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy / Hase (A) Ambulance

Colour:

Silver A/C: Insured / Std / NI / NA

Sp. Reading

92332 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

G04 22. 32004161

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F: 195R15XR  
R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

19/11/24

D.O.I.

26/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

1st N/S &amp; O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

F. P. A. S.

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$



# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

## GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co Reg No: 198003963G

Page 1 / 3

### ESTIMATE

Date	: 25/11/2024	Reg No	: SNE3280X
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: TOYOTA HIACE
Attn.	:	Chassis No	: GDH2232004161
Office / Mobile	:	Engine No	: 1GD8847913
Email Address	:	Quotation No.	: 222813
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/11/2024
Attn.	: KONYINSIEW	Policy No.	: D22MFL0004207_02
Office / Mobile	: +65 6861 0007	Claim Type	: TP CLAIM - CHINA TAIPING
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: ANG MO KIO

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BONNET <i>K X</i>	1	0.00	0	0.00	0.00
2		FRONT BONNET HINGE LH <i>M X</i>	1	0.00	0	0.00	0.00
3		FRONT BONNET HINGE RH <i>K X</i>	1	0.00	0	0.00	0.00
4		LH FRONT CORNER PANEL <i>K X</i>	1	0.00	0	0.00	0.00
5		FRONT GRILLE UPPER <i>?</i>	1	0.00	0	0.00	0.00
6		FRONT GRILLE LOWER <i>CM</i>	1	0.00	0	0.00	0.00
7		FRONT GRILLE INNER BASE <i>?</i>	1	0.00	0	0.00	0.00
8		HEADLAMP LH <i>M/CM</i>	1	0.00	0	0.00	0.00
9		HEADLAMP RH <i>Sux</i>	1	0.00	0	0.00	0.00
10		FRONT BUMPER <i>CM</i>	1	0.00	0	0.00	0.00
11		FRONT BUMPER RETAINER LH <i>M/CM</i>	1	0.00	0	0.00	0.00
12		FRONT BUMPER RETAINER RH <i>?</i>	1	0.00	0	0.00	0.00
13		FRONT BUMPER GRILLE LH <i>Sux</i>	1	0.00	0	0.00	0.00
14		FRONT BUMPER GRILLE RH <i>Sux</i>	1	0.00	0	0.00	0.00
15		RH FRONT DOOR <i>M</i>	1	0.00	0	0.00	0.00
16		RH FRONT DOOR HINGE UPPER <i>K X</i>	1	0.00	0	0.00	0.00
17		RH FRONT DOOR HINGE LOWER <i>K X</i>	1	0.00	0	0.00	0.00
18		RH FRONT DOOR SIDE STEP <i>Sux</i>	1	0.00	0	0.00	0.00
19		FRONT SUPPORT PANEL <i>?</i>	1	0.00	0	0.00	0.00
20		FRONT SUPPORT PANEL BRACKET LH <i>?</i>	1	0.00	0	0.00	0.00
21		FRONT SUPPORT PANEL BRACKET RH <i>?</i>	1	0.00	0	0.00	0.00
22		FRONT SUPPORT PANEL CENTER BRACKET <i>?</i>	1	0.00	0	0.00	0.00

PARTS TOTAL : 0.00

*NOT Withheld  
Repairing B4 pain  
3 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





## ESTIMATE

Date	: 25/11/2024	Reg No	: SNE3280X
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: TOYOTA HIACE
Attn.	:	Chassis No	: GDH2232004161
Office / Mobile	:	Engine No	: 1GD8847913
Email Address	:	Quotation No.	: 222813
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/11/2024
Attn.	: KONYINSIEW	Policy No.	: D22MFL0004207_02
Office / Mobile	: +65 6861 0007	Claim Type	: TP CLAIM - CHINA TAIPING
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: ANG MO KIO

### SPECIAL NETT ITEMS

1	OUTER UNDER VIEW MIRROR GARNISH COVER SET (AFTER MARKET)	1	250.00	7
2	HEADLAMP GARNISH COVER SET (AFTER MARKET)	1	300.00	Na
3	COMPANY BODY STICKER	1	500.00	300.00
4	RH FRONT WHEEL ALUMINIUM COVER	1	680.00	Na
5	RH FRONT TYRE (BRIDGESTONE 195/R15)	1	120.00	X

PARTS TOTAL: 1850.00

### LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	1800.00	1500
2	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM, ETC	350.00	200
3	TO TRANSFER, CHECK, RECONNECT ALL NECESSARY WIRING SYSTEM AND FUNCTIONALLY	150.00	300
4	TO CONDUCT 4 WHEEL ALIGNMENT	150.00	600
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1400.00	900

LABOUR TOTAL : 3,850.00

SUB-TOTAL : 5,700.00

GST @ 9% for \$ 5,700.00 513.00

**GRAND TOTAL (\$\$) :** 6,213.00

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of First Submission	20/11/2024 14:30 (SGT)
Reported by	Actual Driver
Date of Accident	19/11/2024 05:30 (SGT)
Exact Location of Accident	420 Ang Mo Kio Ave 10, Singapore
Additional Location Information	CAR PARK
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNE3280X
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	GOODWILL AMBULANCE SERVICES PTE LTD
Company Reg No	1XXXXX888G
Email Address	INFO@GOODWILLAMBULANCE.COM
Mobile Phone No	(Phone) +65-92995542
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2754
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

### INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D22MFL0004207_02

### DRIVER





**SINGAPORE  
POLICE FORCE**



T/20241119/2023

2 of 3

Report No. T/20241119/2023

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999

**CONTINUATION OF REPORT**

**Brief Details.**

On 19/11/2024 at around 0815hrs, my neighbor alerted me that my ambulance had been involved in a hit-and-run accident and he saw one car (SGT6995B, driver was in a white top) hit unto the front left side of my ambulance. Due to this it caused my ambulance to hit another party (SGY3854T). Traffic police was activated to scene and was able to establish where the defendant stayed however there was no response from the unit. The front left side of my ambulance has dents and parts of it are cracked as well. Traffic Police IO Haslinda then advised me to lodge a traffic accident report regarding this issue. My ambulance was parked at carpark lot 726 Blk 420 Ang Mo Kio