

ESTIMATE

Our Ref: C20240103/TP-CHINATAIPING

Date of Survey: 28/11/2024

Vehicle.: YQ3459E ISUZU NJR88AUE4A AMT

Date Of Loss: 8/11/2024

Chassis no. JAANJR88EM7100007

Surveyor: LKK

<u>S/N</u>	<u>Qty</u>	<u>Description</u>	<u>Rate</u>	<u>Amount \$</u>
<u>Parts</u>				
1	1	Deck Door LH	R	500.00 X
2	2	Deck Door LH hinges	80.00 11	160.00 X
3	1	Rear mud guard LH	su	140.00 X
Sub-Total				800.00
Less 20%				(160.00)
Total Parts				960.00
<u>Special Nett</u>				
4	1	Side protector frame LH	Surf	550.00 500
5	1	Metal rim 14	n	200.00 X
6	1	Tyre 14	kur put	240.00 X
Total Nett				550.00
<u>Labour charges</u>				
5		Panel beating		600.00 300
6		Respray affected area		600.00 300
Total Labour				1,200.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 2,710.00

Not Authorized
her
mercy
28/11/24
the 2nd Attorney
912 \$1100
2 hrs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: