

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

LIBERTY INSURANCE PTE LTD	PRE-REPAIR INSPECTION REPORT					
#25-01 NORTH TOWERSINGAPORE 048583 ATTN: ANDY SEAH Code: LIP 1.		LIBERTY INSURANCE PTE LTD		Ref:	CS3/LIP24110467/Anh3m4(N)	
Insured Veh. GBE 5150S Veh. Inspected GBJ 2091Y				Date:	06/02/2025	
Insured Veh. GBE 5150S		ATTN: ANDY SEAH		Code:	LIP	
Policy No.	1.	Policy Particulars :- (THIRD PARTY CLAIM)				
Claim No. AVS24/3606 Excess (\$) 0.00 Assign From ANDY SEAH Assign Date 21/11/2024 2. Vehicle Particulars & Condition Make & Model NISSAN NV200 c.c 1597 Engine No. HIDDEN Year of Reg. Chassis No. VM20129432 Colour SILVER Odometer 123253 KM Steering IN ORDER Brakes IN ORDER Modification NIL General GOOD 3. Conditions of Tyres		Insured Veh.	GBE 5150S	Veh. Inspected	GBJ 2091Y	
Assign From ANDY SEAH Assign Date 21/11/2024 2. Vehicle Particulars & Condition Make & Model NISSAN NV200 C. C 1597 Engine No. HIDDEN Year of Reg. Chassis No. VM20129432 Colour SILVER Odometer 123253 KM Steering IN ORDER Brakes IN ORDER Modification NIL General GOOD 3. Conditions of Tyres Nake Balance		Policy No.		Coverage (\$)	0.00	
Make & Model NISSAN NV200 C.C 1597		Claim No.	AVS24/3606	Excess (\$)	0.00	
Make & Model NISSAN NV200 C.C 1597		Assign From	ANDY SEAH	Assign Date	21/11/2024	
Engine No.	2.		Vehicle Part	iculars & Condition		
Chassis No. VM20129432 Colour SILVER Odometer 123253 KM Steering IN ORDER Brakes IN ORDER Modification NIL General GOOD 3. Conditions of Tyres Size Make Balance		Make & Model	NISSAN NV200	c.c	1597	
Odometer		Engine No.	HIDDEN	Year of Reg.		
Brakes IN ORDER Modification NIL General GOOD 3. Conditions of Tyres Size Make Balance		Chassis No.	VM20129432	Colour	SILVER	
General GOOD 3. Conditions of Tyres Size Make Balance		Odometer	123253 KM	Steering	IN ORDER	
3. Conditions of Tyres Size		Brakes	IN ORDER	Modification	NIL	
R/H Front Tyre 175/70R14C BLACKHAWK 6 mm L/H Front Tyre 175/70R14C BLACKHAWK 6 mm R/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIRE STIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair		General	GOOD			
R/H Front Tyre 175/70R14C BLACKHAWK 6 mm L/H Front Tyre 175/70R14C BLACKHAWK 6 mm R/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair	3.	Conditions of Tyres				
L/H Front Tyre 175/70R14C BLACKHAWK 6 mm R/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000			Size	Make	Balance	
R/H Rear Tyre 175/70R14C BLACKHAWK 6 mm L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIRE STIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000		R/H Front Tyre	175/70R14C	BLACKHAWK	6 mm	
L/H Rear Tyre 175/70R14C BLACKHAWK 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000		L/H Front Tyre	175/70R14C	BLACKHAWK	6 mm	
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair		R/H Rear Tyre	175/70R14C	BLACKHAWK	6 mm	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000		L/H Rear Tyre	175/70R14C	BLACKHAWK	6 mm	
5. General Information Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000	4.	Description of Damages				
Accident Date 19/11/2024 Inspect Date / Time 21/11/2024 (04:39 PM) Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair						
Survey held at KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair	5.	General Information				
3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair		Accident Date	19/11/2024	Inspect Date / Time	21/11/2024 (04:39 PM)	
SINGAPORE 489978 5a. Remarks A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair		Survey held at	KT MOTORWERK			
A)REGISTRATION DATE: 08 FEB 2019 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair						
B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$16,000 5b. Estimate Days of Repair	5a.	Remarks				
		B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,534.00=NETT VALUE: \$30,466.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
ESTIMATED NORMAL DEDICTO FOR DEDAID. 12 Working Days	5b.	. Estimate Days of Repair				
LOTIMATED NORWALT ENIOD FOR INLINANCE.		ESTIMATED NORM	MAL PERIOD FOR REPAIR:	12 Wor	king Days	

Report Ref No. CS3/LIP24110467/Anh3m4(N)

Inspected By

ADRIAN LING WAI PING

Licensed Appraiser

h

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.