



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110469/Uvh3e2
75 BRAS BASAH ROAD	Date:	11/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 6155S	Veh. Inspected	SGL 4588Z
Policy No.	-	Coverage	0
Claim No.	MT/1305064-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	21/11/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA (A)	C.C	1496
Engine No.	2NR8539476	Year of Reg.	08/01/2016
Chassis No.	NSP1707009755	Colour	RED
Odometer	178920 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/50ZR16	KUMHO	6
L/H Front Tyre	205/50ZR16	KUMHO	6
R/H Rear Tyre	205/50ZR16	KUMHO	6
L/H Rear Tyre	205/50ZR16	KUMHO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/11/2024	Inspection Date	22/11/2024 (11:02)
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days