

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523

not Authorized
 not
 means
 22/11/24
 1/5 #10,000
 clear photo after repair
 10 days

The Motor Claims Dept.

ESTIMATE

INCOME INSURANCE LIMITED
 75 BRAS BASAH ROAD
 SINGAPORE 189557
SME6155S

VEHICLE NO : SGL4588Z
 MAKE/MODEL : TOYOTA SENTIA
 ACC DATE : 19.11.2024

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
	<u>LIST PRICE</u>		
1	1 FRONT BONNET	940.70	3ut/suc 940.70 ✓
2	1 FRONT BONNET LOCK	181.63	su 181.63 X
3	2 FRONT BONNET HINGE RH/LH	89.55	su 179.10 X
4	1 FRONT BUMPER	659.60 515.20	2ut/suc 659.60 ✓
5	1 FRONT BUMPER LOGO	68.80	ner 68.80 ✓
6	1 FRONT BUMPER SPONGE	130.90	11 130.90 X
7	1 FRONT BUMPER TOP BEAM	151.60	su 151.60 X
8	1 FRONT BUMPER REINFORCMENT	552.70	R 552.70 X
9	2 FRONT BUMPER SIDE RETAINER RH/LH	55.10	11 110.20 X
10	1 FRONT GRILLE ASSY	1,210.50 947.50	crn 1,210.50 ✓
11	2 FRONT HEADLAMP RH/LH	1,551.30	crn 3,102.60 ✓
12	1 FRONT SUPPORT PANEL	891.60	R 891.60 X
13	1 FRONT SUPPORT PANEL GARNISH	126.60	su 126.60 X
14	1 REAR TAILGATE	1,726.30 1563.20	body 1,726.30 ✓
15	1 (SET) REAR TAILGATE GLASS MOUDLING	161.95	ner 161.95 ✓
16	1 REAR TAILGATE LOGO	89.95	ner 89.95 ✓
17	1 REAR TAILGATE OUTER GARNISH	291.33	crn 291.33 ✓
18	2 REAR TAILGATE LAMP RH/LH	481.95	11 963.90 X
19	1 REAR TAILGATE INNER LOCK	581.63	page 581.63 ✓
20	1 REAR TAILGATE INNER TRIM	361.60	11 361.60 X
21	1 REAR TAILGATE WEATHERSTRIP	311.42	1w1 311.42 ✓
22	2 REAR TAILGATE DAMPER RH/LH	218.90	11 437.80 X
23	2 REAR TAILLAMP RH/LH	520.10	11 1,040.20 X
24	1 REAR BUMPER	691.60 548.20	dis 691.60 ✓
25	1 REAR BUMPER PAD -CTR	372.45	dis 372.45 ✓
26	2 REAR BUMPER SIDE PAD RH/LH	241.50	dis 483.00 ✓
27	2 REAR BUMPER SIDE RETAINER RH/LH	65.50	11 131.00 X
28	2 REAR BUMPER REFLECTOR RH/LH	89.95	ols/no 179.90 12C
29	2 REAR BUMPER SIDE BRACKET RH/LH	91.50	11 183.00 X
30	1 REAR END PANEL	781.90	body 781.90 ✓
		BALANCE B/F	17,095.46

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE		AMOUNT	
QTY			S\$		S\$
		BALANCE C/F			17,095.46
31	1	REAR END PANEL INNER MEMBER	540.00 871.60	B. J. 200	871.60 ✓
32	1	REAR END PANEL TOP GARNISH	281.63	D.S	281.63 ✓
33	1	REAR FLOOR BOARD	591.50	616	591.50 X
34	1	REAR FLOOR TRAY	481.95	1001	481.95 ✓
35	1	REAR FLOOR PANEL	1,055.60	R	1,055.60 X
36	2	REAR FENDER INNER TRIM BOARD RH/LH	876.50	del 1001	1,753.00 ✓
					22,130.74
		LESS 25%			5,532.69
					16,598.06

SPECIAL NETT ITEMS

1	1	(SET) FRONT BUMPER CLIP	50.00	ner	50.00 30 S/N
2	1	(SET) FRONT NUMBER PLATE	60.00	Che	60.00 40 S/N
3	1	(Set) TAILGATE GLASS SEALANT	80.00	ner	80.00 40 S/N
4	1	(Set) TAILGATE INNER TRIM CLIP	60.00	11	60.00 X
5	1	(SET) REAR BUMPER CLIP	50.00	ner	50.00 30 S/N
6	1	REAR REVERSE SENSOR	280.00	malfunction	280.00 200 S/N
7	1	(SET) REAR NUMBER PLATE	60.00	300	60.00 40 S/N
					640.00

LABOUR CHARGES :

1	TO CHECK FRONT AND REAR ELECTRICAL WIRING	80.00 30
2	TO TRANSFER REAR TAILGATE GLASS	180.00 120
3	TO REMOVE AND REFIX REAR INTERIOR TRIMS	150.00 60
4	TO TUFF KOTE	80.00 ✓
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,800.00 1600
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGE PARTS	1,800.00 1200
	TOTAL:	4,090.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 21,328.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 1390336
25%
10427.52
380
3090
13897.52
202
11118'