

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Gsn Kim Siong (98583398)

Accident Date : 12-Nov-24

Vehicle No : FBH813E (COE: 010313-290228)

Vehicle Model :

Yamaha
Jupiter 135
Manual

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy <i>SVC</i>	\$ 640.00X
1	Fork under bracket <i>11</i>	\$ 280.00X
1	Handle-bar <i>Buf</i>	\$ 168 220.00✓
1	Handle bar inner bracket <i>11</i>	\$ 200.00X
1	Handle-bar end (1 set) <i>cut</i>	\$ 40 120.00✓
1	Hand grip (1 set) <i>11</i>	\$ 95.00X
1	Headlamp <i>SVC</i>	\$ 380 480.00✓
1	Side mirror (1 set) <i>cut</i>	\$ 60 140.00✓
1	Brake lever <i>cut</i>	\$ 125.00✓
1	Fairing assy (1 set) <i>one/cut</i>	\$ 625.00✓
1	Front footrest bracket <i>Buf</i>	\$ 126 280.00✓
2	Front footrest rubbers <i>Torn/Free</i>	20x2=\$ 60 100.00✓
1	Brake pedal <i>cut</i>	\$ 125 220.00✓
1	Exhaust assy <i>R</i>	\$ 1,800.00X
1	Exhaust protector <i>cut</i>	\$ 148 165.00✓
1	Rear rim <i>R</i>	\$ 580.00X
1	Rear reflector <i>Bro</i>	\$ 45 145.00✓
1	Rear swing arm <i>Buf/Free</i>	\$ 685.00✓
1	Rear lamp <i>one</i>	\$ 280 385.00✓
1	Rear fender <i>one</i>	\$ 140 285.00✓
2	Rear footrests <i>SVC</i>	\$ 180.00X
2	Rear footrest brackets <i>0/Scro</i>	\$ 110 420.00 1PC
		\$ 8,170.00
	Less 10%	\$ 817.00
		\$ 7,353.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Gsn Kim Siong (98583398)

Accident Date : 12-Nov-24

Vehicle No : FBH813E (COE: 010313-290228)

Vehicle Model :

Yamaha
Jupiter 135
Manual

Estimated Repair Costs

Special Net Items

1	Rear Number plate - 1 set	buf	\$	38.00	20
2	Fork oils	11	\$	30.00	X
2	Fork oil seals	11	\$	56.00	X
1	Steering cone (1 set)	11	\$	150.00	X
1	Sticker	bu	\$	120.00	60
1	Rear box	ur	\$	480.00	400
1	Rear box bracket	su	\$	180.00	X
				\$	1,054.00

S/No. Labour

1	To provide towing service (LOD) \$70.00	refer to LOD	\$	-	X
2	To check wiring and reset headlamp focusing		\$	11	80.00 X
3	To repair body frame		\$	11	520.00 X
4	To provide labour		\$	420.00	300
				\$	1,020.00

Grand Total

\$ 9,427.00

Singapore Dollars: Nine Thousand Four Hundred and Twenty-Seven only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-3117
102
2805.30
480
300
3585.30