

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110472/UMA3Q2**Date:** 11/12/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900163979
Claimant Vehicle No : SKP2995B **Insured Vehicle No :** YQ1478M
 Date of Loss: 21/11/2024 Nature of Claim: TP Claim No: 9682784566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP2995B**
 Make & Model: VOLKSWAGEN GOLF, 1.4 A7 TSI 5G13GZ Engine No: CXS214202
 W/O HID (A)
 Reg. Date: 28/08/2014 (Man. Year: 2014) Chassis No: WVVZZZAUZFW030535
 Colour: White Odometer: 103607 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,168.59	4,275.98	8,892.61	67.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,030.00	2,530.00	71.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,728.59	5,305.98	11,422.61	68.28
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	16,728.59	4,200.00	12,528.59	74.89
+ GST 9.00/9.00% (S\$)	1,505.57	378.00	1,127.57	74.89
Nett Amount (S\$)	18,234.16	4,578.00	13,656.16	74.89
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
(S\$)		4,878.00		
Liabe Amount (50.00%) (S\$)		2,439.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,466.25		
Global Sum Settlement (S\$)		2,450.00		

INSPECTION

Date of Assignment: 22/11/2024

Date Inspected: 22/11/2024 Inspected At:

SPEEDWERKZ PTE LTD (Autobay) (HQ)
 1 KAKI BUKIT AVENUE 6 #01-73
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	769.10 FL	*- FL
2	1		*FRONT RIM RH	Not Necessary	1,846.00 FL	*- FL
3	1		*FRONT LOWER ARM RH	Not Necessary	678.10 FL	*- FL
4	1		*FRONT KNUCKLE ARM RH	Not Necessary	973.25 FL	*- FL
5	1		*FRONT KNUCKLE BEARING RH	Not Necessary	851.30 FL	*- FL
6	1		*FRONT SHOCK ABSORBER RH	Not Necessary	478.50 FL	*- FL
7	1		*FRONT DOOR RH	Badly Dented	2,224.60 FL	*1,615.00 FL
8	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	166.20 FL	*- FL
9	1		*FRONT DOOR OUTER GLASS MOULDING RH	Not Necessary	134.80 FL	*- FL
10	1		*FRONT DOOR INNER GLASS SEAL RH	Not Necessary	87.90 FL	*- FL
11	1		*FRONT DOOR OUTER HANDLE RH	Broken	756.19 FL	*280.00 FL
12	1		*FRONT DOOR LOCK CYLINDER WITH HOUSING	Broken / Damaged	419.95 FL	*305.00 FL
13	1		*FRONT DOOR OUTER HANDLE CAP RH	Broken	56.40 FL	*56.40 FL
14	1		*FRONT DOOR INNER LOCK RH	Not Necessary	343.64 FL	*- FL
15	1		*FRONT DOOR SIDE MIRROR RH	Damaged	889.69 FL	*889.69 FL
16	1		*FRONT DOOR SIDE MIRROR COVER RH	Not Necessary	257.40 FL	*- FL
17	1		*REAR DOOR RH	Dented / Bent	2,431.20 FL	*1,605.00 FL
18	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	166.20 FL	*- FL
19	1		*REAR DOOR OUTER GLASS MOULDING RH	Not Necessary	134.80 FL	*- FL
20	1		*REAR DOOR INNER GLASS SEAL RH	Not Necessary	87.90 FL	*- FL
21	1		*REAR DOOR OUTER HANDLE RH	Repair	234.20 FL	*- FL
22	1		*FRONT FENDER INNER SPLASH SHIELD RH CLIPS	Not Necessary	70.00 FS	*- FS
23	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
24	1		*FRONT DOOR TRIMBOARD RH CLIPS	Not Necessary	80.00 FS	*- FS
25	1		*REAR DOOR TRIMBOARD RH CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,567.32	4,751.09
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,398.73	475.11
Total Parts (\$\$)	13,168.59	4,275.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE LABOUR WORKMANSHIP	New	1,400.00	280.00
2	TO SPRAY PAINT ON AFFECTED PANELS	New	1,000.00	600.00
3	RUST PROOFING	New	80.00	50.00
4	TO REMOVE ,REFIT & TRANSFER FRONT & REAR RIGHT DOORS TO	New	160.00	100.00
5	TO REMOVE ,REPLACE FRONT RH SIDE MIRROR	New	80.00	0.00
6	TO CONDUCT COMPUTERISE DIAGNOSTIC ,RESET AND	New	360.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
8	TO REMOVE & REPLACE FRONT RIGHT TYRE AND BALANCING	New	80.00	0.00
9	TO REMOVE AND REPLACE FRONT RIGHT UNDERCARRIAGE	New	280.00	0.00
Gross Labour Cost (\$\$)			3,560.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >