

Not Notified
 1/12/12 @ 1200h
 Resurvey Blk pain

VEHICLE NO: SNQ7976H

MODEL: TOYOTA CAMRY 2.5

CHASSIS NO: MR053AK5004012615

2. days

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
REAR BUMPER <i>1011.50</i>	<i>Br/cn</i> \$ 1,150.00 ✓
REAR BUMPER SIDE RETAINER LHS	\$ <i>sn</i> 180.00 X
REAR BUMPER SIDE RETAINER RHS	\$ <i>sn</i> 180.00 X
REAR BUMPER REINFORCEMENT BAR	\$ <i>rn</i> 650.00 Z
REVERSE SENSOR CENTER LHS	\$ <i>sn</i> 550.00 Z
REVERSE SENSOR CENTER RHS	\$ <i>rn</i> 550.00 X
END PANEL	\$ <i>rn</i> 1,070.00 X
END PANEL TOP GARNISH	\$ <i>sn</i> 510.00 X
	25% \$ 4,840.00
	\$ 1,210.00
	\$ 3,630.00
<u>SPECIAL NETT ITEMS</u>	
REAR BUMPER CLIPS 1 SET	\$ <i>rn</i> 60.00 ✓
BODY SEALANT	\$ <i>nn</i> 60.00 X
Total	\$ 120.00
TOTAL PARTS	\$ 3,750.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commen repairs; replace damaged parts and components	\$ ^{300/-} 1,200.00
2	To supply paint materials, expandable items & put respray paint on parts replaced & repaired	\$ ^{200/-} 1,000.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ <i>nn</i> 100.00 X
4	To provide anti-rust treatment on affected areas	\$ <i>nn</i> 100.00 X
5	Dignostic Check	\$ <i>nn</i> 100.00 X
	Labour Total :	\$ 2,500.00
	TOTAL (PARTS & LABOUR):	\$ 6,250.00