






**CYCLE & CARRIAGE FRANCE PTE. LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



**CITROËN**

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
REYMON GOH SWEE BOON		Cust No/Name /REYMON GOH SWEE BOON	
BLK 21 PASIR RIS STREET 72		Reg No/Reg Date SNF3141J / 20/05/2022	
#11-02		Date In/Mileage / 0	
SINGAPORE 518764		Chassis No VR7BAHNSBME056010	
Contact No Mobile: 82283586		Engine No 10XVDW1856546	
		Make/Model CIT/C4 FEEL 1.2 PURETECH 130	
		Colour/Trim MOF ARTIC STEEL / SOF URBAN GREY FABR	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00077	Cash	20/11/2024/ 11:22		1015/ Vikneswaran Naidu A	10544			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								760 3040.00
RENEW RR BUMPER, LWR BUMPER, REPAIR TAILGATE, REPAIR END PANEL AND RENEW DAMAGED PARTS								550 1750.00
E PNT98000								✓ 380.00
SPRAY RR BUMPER, TAILGATE, END PANEL								✓ 100.00
A 10028901								100 150.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								X 100.00
A 10028901								100 150.00
CHECK WIRING AND ELECTRICAL								X 100.00
E PNT88000								X 100.00
REMOVE AND REFIT SENSOR								50 120.00
M SUNDRY								X 150.00
SUPPLY NUMBER PLATE REAR								40 80.00
M SUNDRY								? 790.00
APPLY SEALANT ON AFFECTED AREA								del 529.00
M SUNDRY								? 94.00
ANTI RUST PROOFING								dis 477.00
M SUNDRY								? 162.00
SUNDRIES					1.00	790.00	0.00	rel 124.00
M REAR BUMPER					1.00	529.00	0.00	rel 124.00
M BUMPER SKIRT					1.00	94.00	0.00	? 554.00
M RECESS DOOR					1.00	477.00	0.00	X 66.00
M BUMPER SKIRT IN					1.00	162.00	0.00	X 66.00
M BUMPER BRACKET					1.00	124.00	0.00	
M BUMPER BRACKET					1.00	124.00	0.00	
M BUMPER BRACKET					1.00	554.00	0.00	
M BUMPER ABSORBER					1.00	66.00	0.00	
M MONOGRAMME					1.00	66.00	0.00	
M MONOGRAMME					1.00	66.00	0.00	

**Estimate**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

nature:

Estimate

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
nature:

Confirm & accepted by

Taufik 97495749/62563561  
12/12/24 21030 03 days  
'wp' taufik@kkkauto.com

Authorized signatory and company stamp

Parts	2,986.00
Labour	5,420.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	450.00
Total(w/o GST)	8,856.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.