

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP INC

Veron

2023

ESTIMATE OF REPAIR

Veh# : SNK3858Z

Accident Date : 10/1/2025

Location : UBI ROAD 3

Model:

BYD E6

10/4/2023 - 9/4/2033

3P:

SJW5636T (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bonnet <i>Distorted</i>	958.00	✓	
2	2 pcs	Front bonnet hinges R/L <i>Bent</i>	120.00	✓	
3	2 pcs	Front bonnet damper R/L <i>Not new</i>	230.00	X	
4	1 pc	Front bonnet insulator <i>replaced</i>	145.00	✓	
5	1 set	Front bonnet insulator clip <i>new</i>		50.00	30
6	1 pc	Front bonnet lock <i>Jammed</i>	100.00	✓	
7	1 pc	Front bonnet rubber seal <i>new</i>	35.00	X	
8	1 pc	Front bonnet lock cable <i>Jammed</i>	90.00	✓	
9	1 pc	Front grille <i>cracked</i>	316.00	✓	
10	1 pc	Front grille Logo <i>new</i>	80.00	✓	
11	1 pc	Front grille rubber seal <i>not new</i>	30.00	X	
12	1 pc	Front grille top cover <i>Delivered</i>	210.00	✓	
13	1 set	Front grille top cover clip <i>new</i>		40.00	20
14	2 pcs	Front headlamp R/L <i>cracked</i>	1,900.00	✓	
15	1 pc	Front bumper <i>Distorted</i>	672.00	✓	
16	1 set	Front bumper clip <i>new</i>		50.00	30
17	1 pc	Front bumper reinforcement <i>Bent</i>	624.00	✓	
18	1 pc	Front bumper foglamp cover LH <i>Not new</i>	42.00	X	
19	1 pc	Front bumper lower grille <i>Delivered</i>	135.00	✓	
20	1 pc	Front bumper lower grille cover LH <i>Not new</i>	50.00	X	
21	1 pc	Front bumper lower cover <i>Not new</i>	130.00	X	
22	1 pc	Front bumper inner approach horn <i>cracked</i>	180.00	✓	
23	2 pcs	Front bumper inner garnish R/L <i>Delivered</i>	100.00	✓	
24	2 pcs	Front bumper side retainer R/L <i>Not new</i>	90.00	X	
25	1 pc	Front no. plate <i>Bent</i>		35.00	✓

26	1 pc	Front no. plate holder <i>Dehd</i>		50.00	30
27	1 pc	Front no. plate bracket garnish <i>Dehd</i>	102.00	✓	
28	1 pc	Front support panel <i>Creed</i>	865.00	✓	
29	1 pc	Air-con condenser <i>Dehd</i>	1,150.00	✓	
30	1 pc	Radiator (Auto) <i>Dehd</i>	1,210.00	✓	
31	1 pc	Radiator coolant <i>new</i>		60.00	✓
32	2 pcs	Front fender R/L (Repair) <i>Rys</i>		X	
33	1 pc	Radiator fan motor Assy <i>Dehd</i>	685.00	✓	
34	2 pcs	Air-con condenser garnish R/L <i>Dehd</i>	102.00	✓	
35	1 pc	Air-con condenser discharge hose <i>at</i>	119.00	✓	
36	1 pc	Front horn LH <i>Dehd</i>	65.00	✓	2003.00?
		<i>9928</i> Sub Total:	10,535.00	285.00	0.00
		<i>8935.00</i>	10%	0%	0%
		<i>86 N. 205</i> After Less %:	9,481.50	285.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign accident affected area.		1,000.00	800
2		To spray paint on accident affected area.		1,200.00	700
3		To remove & refix air-con condenser, hose & refilling gas.		150.00	120
4		To check wiring & headlamp focus.		50.00	30
		<i>1650</i> Sub Total:		2,400.00	
		Total:		12,166.50	1650

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "24 hr accident call" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mobil 1

Admin C
L/S 14/01/25
07 Days
total: 1079020
L/S : 8610