

UP

ASSIGNMENT

	TOTAL	

MeNutMotor

5 Soon Lee Street
 #02-04 Pioneer Point
 Singapore 627607

TO
 M/s Liberty Insurance

FOR Aerox
 FBM9967J

Description		Amount
Rear mudguard	CNA ✓	\$110.00
Rear signal light	?	\$80.00
Rear plate number	bt ✓	\$50.00
Workmanship	/	\$120.00
LTA search	?	\$27.25
Administrative (phone calls/emails/messages with third party insurance company)	?	\$30.00
Total		\$417.25

417.25 Payment Mode:

PayNow to UEN No: 53458672D

Bank transfer to DBS Account No. 0729095264

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanjik 97495749
 'wp' 04/07/24
 Resurvey new parts
 1 day
 tanjik@lkkauto.com