

MeNutMotor

5 Soon Lee Street
#02-04 Pioneer Point
Singapore 627607

TO
M/s Liberty Insurance

FOR Aerox
FBM9967J

Description	Amount
Rear mudguard	crn ✓ \$110.00
Rear signal light	nn X \$80.00
Rear plate number	bt ✓ 30 \$50.00
Workmanship	/ \$120.00
LTA search	x \$27.25
Administrative (phone calls/emails/messages with third party insurance company)	x \$30.00
Total	\$417.25

417.25 Payment Mode:

PayNow to UEN No: 53458672D

Bank transfer to DBS Account No. 0729095264

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanjik 97495749
-wp- 04/07/24
Resurvey new parts
1 day
tanjik@lkkauto.com

Parts 140
10% - 126
labour - 120
\$ 246
* 01 day