

REF:

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP / RES / OD RES / EVA / INV / MV

To in _____ Vehicle NO: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Mtar. Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: JNA253 Yr Regn: 2008, Dec

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Camry C.D. 1998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 81056 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53 BK4107004-828

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / IZA / MG / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm

D.O.A. _____ D.O.I. 19/11/24

Survey held at: HD Perfect.

Des. of Damages: Frt / Rear / OIS / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TR ALG</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey : Yes (✓) No ()</u>
	<u>MV : 31K (RM)</u>
	<u>PV : 2K (RM)</u>
	<u>Nett : 29K (RM) ≈ 9K</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____

Photos

Others

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Inve (\$)

Report Format: _____

Report No: _____

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **JNA253**
 MODEL : **TOYOTA CAMRY**
 DATE OF ACCIDENT : 17.11.2024
 TIME OF ACCIDENT : 13:05 HOURS

28	REAR FENDER INNER COWLING <i>new</i>	2	\$ 405.00	\$ 810.00	+
29	REAR FENDER INNER TRIM <i>new</i>	2	\$ 675.00	\$ 1,350.00	+
31	REAR END PANEL <i>Dented</i>	1	\$ 620.00	\$ 620.00	✓
32	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 420.00	\$ 420.00	✓
33	REAR FLOOR PANEL TOP BOARD <i>to r</i>	1	\$ 280.00	\$ 280.00	✓
34	REAR FLOOR PANEL <i>to r Buckled</i>	1	\$ 1,140.00	\$ 1,140.00	✓
36	REAR FLOOR SIDE PANEL RH <i>to r</i>	1	\$ 586.20	\$ 586.20	+
37	REAR SPARE TYRE BOLT <i>to r</i>	1	\$ 32.00	\$ 32.00	+
24	CENTER EXHAUST <i>to r</i>	1	\$ 1,425.00	\$ 1,425.00	+
25	CENTER EXHAUST INSULATOR <i>to r</i>	1	\$ 170.00	\$ 170.00	+
26	CENTER EXHAUST GASKET (SET) <i>to r</i>	1	\$ 75.00	\$ 75.00	✓
27	REAR EXHAUST PIPE <i>to r ?</i>	1	\$ 892.10	\$ 892.10	+
28	REAR EXHAUST INSULATOR <i>to r</i>	1	\$ 161.10	\$ 161.10	+
29	REAR EXHAUST GASKET (SET) <i>to r</i>	1	\$ 75.00	\$ 75.00	+
30	REAR EXHAUST MOUNTING <i>to r</i>	2	\$ 39.00	\$ 78.00	+

TOTAL PRICE \$ 14,830.40
 LESS 25% \$ 3,707.60
SUB TOTAL PRICE \$ 11,122.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>to r</i>	1	\$ 80.00	\$ 80.00	30
3	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
5	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	REAR END PANEL INSULATION SEAL <i>to r</i>	1	\$ 150.00	\$ 150.00	60
8	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
9	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200-

TOTAL \$ 1,030.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **JNA253**
 MODEL : **TOYOTA CAMRY**
 DATE OF ACCIDENT : 17.11.2024
 TIME OF ACCIDENT : 13:05 HOURS

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 160.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
9	REMOVE AND REFIX REAR EXHAUST	\$ 180.00	?
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,940.00

TOTAL PARTS COST : \$ 12,152.80
 TOTAL LABOUR COST : \$ 4,940.00
 TOTAL REPAIR COST : \$ 17,092.80

*Adrian L
 2/8 19/11/24
 09 days*

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: