

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 18.11.2024

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **JNA253**  
MODEL : **TOYOTA CAMRY**  
DATE OF ACCIDENT : 17.11.2024  
TIME OF ACCIDENT : 13:05 HOURS

*Daphne*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 910.00	\$ 910.00
2	BOOTLID DETECTOR <i>new</i>	1	\$ 395.00	\$ 395.00
3	BOOTLID LAMP <i>RH cut</i>	2	\$ 420.00	\$ 840.00
4	BOOT LTD EMBLEM 'CAMRY' <i>new</i>	1	\$ 65.00	\$ 65.00
5	BOOT LID EMBLEM '2.0'	1	\$ 60.00	\$ 60.00
6	BOOT LID LOGO	1	\$ 80.00	\$ 80.00
7	BOOTLID HINGE <i>new</i>	2	\$ 126.00	\$ 252.00
8	BOOTLID STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
9	BOOTLID INSULATOR	1	\$ 265.00	\$ 265.00
10	BOOTLID LOCK <i>new</i>	1	\$ 395.00	\$ 395.00
11	BOOTLID CATHER <i>new</i>	1	\$ 25.00	\$ 25.00
12	BOOTLID WEATHERSTRIP <i>ld</i>	1	\$ 240.00	\$ 240.00
13	REAR NUMBER PLATE GARNISH WITH MOULDING <i>new</i>	1	\$ 380.00	\$ 380.00
14	REAR BUMPER <i>Dented</i>	1	\$ 560.00	\$ 560.00
15	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 75.00	\$ 150.00
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 70.00	\$ 140.00
17	REAR BUMPER RETAINER (CORNER) <i>new</i>	2	\$ 80.00	\$ 160.00
18	REAR BUMPER SCREW COVER GARNISH <i>new</i>	2	\$ 28.00	\$ 56.00
19	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 405.00	\$ 405.00
24	TAILLAMP <i>RH cut</i>	2	\$ 535.00	\$ 1,070.00
25	TAILLAMP PANEL RH <i>Repair</i>	1	\$ 230.00	\$ 230.00

✓  
+  
420  
✓  
✓  
-  
+  
+  
+  
-  
+  
+  
✓  
✓  
+  
+  
+  
+  
✓  
535  
+

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **JNA253**  
 MODEL : **TOYOTA CAMRY**  
 DATE OF ACCIDENT : 17.11.2024  
 TIME OF ACCIDENT : 13:05 HOURS

28	REAR FENDER INNER COWLING <i>new</i>	2	\$ 405.00	\$ 810.00	+
29	REAR FENDER INNER TRIM <i>new</i>	2	\$ 675.00	\$ 1,350.00	+
31	REAR END PANEL <i>Deleted</i>	1	\$ 620.00	\$ 620.00	✓
32	REAR END PANEL TOP GARNISH <i>Deleted</i>	1	\$ 420.00	\$ 420.00	✓
33	REAR FLOOR PANEL TOP BOARD <i>ton</i>	1	\$ 280.00	\$ 280.00	✓
34	REAR FLOOR PANEL <i>from Buckled</i>	1	\$ 1,140.00	\$ 1,140.00	✓
36	REAR FLOOR SIDE PANEL RH <i>for</i>	1	\$ 586.20	\$ 586.20	+
37	REAR SPARE TYRE BOLT <i>for</i>	1	\$ 32.00	\$ 32.00	+
24	CENTER EXHAUST <i>for</i>	1	\$ 1,425.00	\$ 1,425.00	+
25	CENTER EXHAUST INSULATOR <i>for</i>	1	\$ 170.00	\$ 170.00	+
26	CENTER EXHAUST GASKET (SET)	1	\$ 75.00	\$ 75.00	✓
27	REAR EXHAUST PIPE <i>for Best</i>	1	\$ 892.10	\$ 892.10	✓
28	REAR EXHAUST INSULATOR <i>for</i>	1	\$ 161.10	\$ 161.10	+
29	REAR EXHAUST GASKET (SET) <i>new</i>	1	\$ 75.00	\$ 75.00	+
30	REAR EXHAUST MOUNTING	2	\$ 39.00	\$ 78.00	+

7402.10  
5551.57

TOTAL PRICE \$ 14,830.40  
 LESS 25% \$ 3,707.60  
**SUB TOTAL PRICE \$ 11,122.80**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
5	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	REAR END PANEL INSULATION SEAL <i>for</i>	1	\$ 150.00	\$ 150.00	60
8	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
9	REVERSE SENSOR <i>changed</i>	1	\$ 220.00	\$ 220.00	200

290

**TOTAL \$ 1,030.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **JNA253**  
 MODEL : **TOYOTA CAMRY**  
 DATE OF ACCIDENT : 17.11.2024  
 TIME OF ACCIDENT : 13:05 HOURS

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 160.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
9	REMOVE AND REFIX REAR EXHAUST	\$ 180.00	60
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2120

**TOTAL \$ 4,940.00**

TOTAL PARTS COST : \$ 12,152.80  
 TOTAL LABOUR COST : \$ 4,940.00  
 TOTAL REPAIR COST : \$ 17,092.80

Adnan L  
 w/s 19/11/24  
 09/11/24

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

total: 7961.57

w/s 0350 ✓