

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2024)
Parts:	M1-COUPE	MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>dt</i>	0	0.00	<i>S/K</i> *35.00 FS
2	1		*FRT NUMBER PLATE HOLDER <i>dt</i>	0.00	0.00	*105.00 F
3	1		*FRT BUMPER <i>dt</i>	0.00	0.00	*1,175.00 F
4	2		*FRT BUMPER RETAINER LH/RH <i>? xsv</i>	0.00	0.00	*20.00 FX
5	1		*FRT BUMPER LOWER CENTER CARRIAGE <i>? xsv</i>	0.00	0.00	*118.00 FX
6	1		*FRT BUMPER LWR CENTER TRIM <i>dt</i>	0.00	0.00	*95.00 FX
7	1		*FRT BUMPER SPONGE <i>? xsv</i>	0.00	0.00	*150.00 FX
8	1		*FRT GRILLE ASSY <i>cu</i>	0.00	0.00	*165.00 F
9	1		*FRT GRILLE OUTER CENTER MOULDING <i>dt</i>	0.00	0.00	*225.00 F
10	4		*FRT GRILLE OUTER CENTER TRIM <i>cu</i>	0.00	0.00	*260.00 F
11	1		*FRT GRILLE OUTER TRIM <i>dt</i>	0.00	0.00	*210.00 F
12	1		*FRT GRILLE EMBLEM <i>dt</i>	0.00	0.00	*105.00 F
13	1		*FRT GRILLE EMBLEM BASE <i>? xsv</i>	0.00	0.00	*78.00 F
14	1		*FRT CAMERA <i>? xsv</i>	0.00	0.00	*1,150.00 FX
15	1		*FRT CAMERA CAP <i>? xsv</i>	0.00	0.00	*10.00 FX
16	2		*FRT PARKING AID SENSOR CENTER LH/RH <i>? xsv</i>	0.00	0.00	*270.00 FX
17	1		*FRT BONNET <i>dt</i>	0.00	0.00	*1,645.00 F
18	1		*FRT BONNET EMBLEM <i>dt</i>	0.00	0.00	*60.00 F
19	2		*FRT HEADLAMP LH/RH <i>RH-1/14-CAN @ 2350</i>	0.00	0.00	*4,700.00 F
20	2		*FRT HEADLAMP LOWER BRACKET LH/RH <i>? xsv</i>	0.00	0.00	*260.00 FX
21	1		*FRT BUMPER LOWER CENTER GARNISH <i>? xsv</i>	0.00	0.00	*105.00 FX
F=Franchise part. S=SpclNett.						
Sub Total (\$\$)				6378		10,941.00
+ Margin on L,N Items 10.00% (\$\$)				10% +		1,090.60
Total Parts (\$\$)				7015.80		12,031.60

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

S/N-35

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	SSO New	400 600.00 +150
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	400 600.00
3	TO CHECK WIRING	New	30 50.00
4	TO DIAGNOSE & RESET FAULT CODE	New	150 200.00
			1180
Gross Labour Cost (S\$)			1,530.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene
Hp 90010068

4 days
4/5

EXCESS = TBA

7015.80

35.00

1180.00

297.00

8527.80

202

6822.24

4/5 - 96,800 / 4 day

Res after
repair