

# Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18  
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email:

sngahtee@singnet.com.sg;darren@sngahtee.com;admin@sngahtee.com;admin2@sngahtee.com

INSURER:

**ECICS Limited (HQ)**

## PARTICULARS OF CLAIM

|                     |                 |                       |             |
|---------------------|-----------------|-----------------------|-------------|
| Claim Type:         | OD (OWN DAMAGE) | Ref. No:              |             |
| Policy No:          | MPC23A00375400  | Date of Loss:         | 19/11/2024  |
| Vehicle Reg. No.:   | SKF6998U        | Driveable?            |             |
| Driver Age/Info:    | 48 / MALE       | Party At Fault:       | UNKNOWN     |
| TP Injury Involved? | NO              | Third Party Involved? | YES         |
| Insured/Claimant:   | ZHOU HAILONG    | Contact No:           | +6590064528 |
| Driver:             | ZHOU HAILONG    |                       |             |

|                 |                             |                    |                   |
|-----------------|-----------------------------|--------------------|-------------------|
| Make/Model:     | MERCEDES-BENZ E300, 2.0 (A) | Vehicle Reg. Date: | 17/12/2019        |
| Vehicle Colour: | WHITE                       |                    |                   |
| Engine No:      | 26492080016553              | Chassis No:        | WDD2130832A728568 |
| Odometer:       | 142235 KM                   |                    |                   |

|                               |    |
|-------------------------------|----|
| Paint Type:                   |    |
| Total Loss?                   | NO |
| Est. Duration of Repair (day) | 8  |

|                              |                                                    |
|------------------------------|----------------------------------------------------|
| Description of Accident/Loss | ON 19/11/2024 @                                    |
| Present Location:            | SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) |

## COST OF CLAIMS

|                          | Amount           |
|--------------------------|------------------|
| Parts                    | 12,031.60        |
| Miscellaneous Items      | 0.00             |
| Labour                   | 1,530.00         |
| Paintwork Labour         | 0.00             |
| Towing                   | 0.00             |
| <b>Gross Total (S\$)</b> | <b>13,561.60</b> |
| <b>+ GST 9.00% (S\$)</b> | <b>1,220.54</b>  |
| <b>Nett Amount (S\$)</b> | <b>14,782.14</b> |

**This claim is handled by: JOYCE TAN LAI CHIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2024)

Parts: M1-COUPE MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                 | %Disc | %Depr | Amount      |
|-----|-----|----------|---------------------------------------------|-------|-------|-------------|
| 1   | 1   |          | *FRT NUMBER PLATE <i>de</i>                 | 0     | 0.00  | *35.00 FS   |
| 2   | 1   |          | *FRT NUMBER PLATE HOLDER <i>de</i>          | 0.00  | 0.00  | *105.00 F   |
| 3   | 1   |          | *FRT BUMPER <i>de</i>                       | 0.00  | 0.00  | *1,175.00 F |
| 4   | 2   |          | *FRT BUMPER RETAINER LH/RH ?                | 0.00  | 0.00  | *20.00 F    |
| 5   | 1   |          | *FRT BUMPER LOWER CENTER CARRIAGE ?         | 0.00  | 0.00  | *118.00 F   |
| 6   | 1   |          | *FRT BUMPER LWR CENTER TRIM <i>de</i> ?     | 0.00  | 0.00  | *95.00 F    |
| 7   | 1   |          | *FRT BUMPER SPONGE ?                        | 0.00  | 0.00  | *150.00 F   |
| 8   | 1   |          | *FRT GRILLE ASSY <i>cm</i>                  | 0.00  | 0.00  | *165.00 F   |
| 9   | 1   |          | *FRT GRILLE OUTER CENTER MOULDING <i>cm</i> | 0.00  | 0.00  | *225.00 F   |
| 10  | 4   |          | *FRT GRILLE OUTER CENTER TRIM <i>cm</i>     | 0.00  | 0.00  | *260.00 F   |
| 11  | 1   |          | *FRT GRILLE OUTER TRIM <i>cm</i>            | 0.00  | 0.00  | *210.00 F   |
| 12  | 1   |          | *FRT GRILLE EMBLEM <i>cm</i>                | 0.00  | 0.00  | *105.00 F   |
| 13  | 1   |          | *FRT GRILLE EMBLEM BASE ?                   | 0.00  | 0.00  | *78.00 F    |
| 14  | 1   |          | *FRT CAMERA ?                               | 0.00  | 0.00  | *1,150.00 F |
| 15  | 1   |          | *FRT CAMERA CAP ?                           | 0.00  | 0.00  | *10.00 F    |
| 16  | 2   |          | *FRT PARKING AID SENSOR CENTER LH/RH ?      | 0.00  | 0.00  | *270.00 F   |
| 17  | 1   |          | *FRT BONNET <i>st</i>                       | 0.00  | 0.00  | *1,645.00 F |
| 18  | 1   |          | *FRT BONNET EMBLEM <i>cm</i>                | 0.00  | 0.00  | *60.00 F    |
| 19  | 2   |          | *FRT HEADLAMP LH/RH <i>RH-?/LH-cm</i>       | 0.00  | 0.00  | *4,700.00 F |
| 20  | 2   |          | *FRT HEADLAMP LOWER BRACKET LH/RH ?         | 0.00  | 0.00  | *260.00 F   |
| 21  | 1   |          | *FRT BUMPER LOWER CENTER GARNISH ?          | 0.00  | 0.00  | *105.00 F   |

F=Franchise part. S=SpcNett.

|                                    |           |
|------------------------------------|-----------|
| Sub Total (S\$)                    | 10,941.00 |
| + Margin on L,N Items 10.00% (S\$) | 1,090.60  |
| Total Parts (S\$)                  | 12,031.60 |

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                  | Lab.Type | Amount                |
|-------------------------|----------------------------------------------|----------|-----------------------|
| <b>Labour Items</b>     |                                              |          |                       |
| 1                       | TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS | New      | 400 <del>600.00</del> |
| 2                       | TO SPRAY PAINTING ON AFFECTEDS AREAS         | New      | 400 <del>600.00</del> |
| 3                       | TO CHECK WIRING                              | New      | 30 <del>50.00</del>   |
| 4                       | TO DIAGNOSE & RESET FAULT CODE               | New      | 150 <del>280.00</del> |
| Gross Labour Cost (S\$) |                                              |          | 1,530.00              |

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rasme*

*Hp 90010068*

*4 days*

*45*

*EXCESS: TBA*

*Revert*

*Reg after  
reply*