

Company Reg No: 202136904Z

E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 19.11.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNE2299A**
MODEL : **MERCEDES BENZ GLB200**
DATE OF ACCIDENT : 19.11.2024
TIME OF ACCIDENT : 09:50 HOURS

W1X24768726034103
Daphne. 2020

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL - PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER (UPPER) <i>Dishbed</i>	1	\$ 1,980.00	\$ 1,980.00
2	REAR BUMPER (UPPER) TOP CHROME <i>mc</i>	1	\$ 1,235.00	\$ 1,235.00
3	REAR BUMPER (LOWER) <i>Dishbed</i>	1	\$ 925.00	\$ 925.00
4	REAR BUMPER CHROME (CENTER) <i>could</i>	1	\$ 1,480.00	\$ 1,480.00
5	REAR BUMPER DIFFUSER <i>Dishbed</i>	1	\$ 652.00	\$ 652.00
6	REAR BUMPER REFLECTOR <i>RM could</i>	2	\$ 78.00	\$ 156.00
7	REAR BUMPER TOWING COVER <i>mc w</i>	1	\$ 95.00	\$ 95.00
8	REAR BUMPER EXHAUST CHROME <i>RM could</i>	2	\$ 158.00	\$ 316.00
9	REAR BUMPER EXHAUST CHROME BRACKET <i>RM Dish</i>	2	\$ 95.60	\$ 191.20
10	REAR BUMPER SENSOR <i>2 pieces Dish</i>	4	\$ 236.00	\$ 944.00
11	REAR BUMPER SENSOR HOLDER <i>2 pieces mc</i>	6	\$ 43.00	\$ 258.00
12	REAR BUMPER SENSOR WIRE HARNESS <i>mc w</i>	1	\$ 268.00	\$ 268.00
13	REAR BUMPER SMART SENSOR CONTROL UNIT <i>could</i>	1	\$ 491.00	\$ 491.00
14	REAR BUMPER SMART SENSOR <i>mc w</i>	1	\$ 285.00	\$ 285.00
15	REAR BUMPER SMART SENSOR C/W CABLE <i>mc w</i>	1	\$ 391.00	\$ 391.00
16	REAR BUMPER SIDE RETAINER <i>mc w</i>	2	\$ 138.00	\$ 276.00
17	REAR BUMPER CENTER TOP BEAM <i>could</i>	1	\$ 280.00	\$ 280.00
18	REAR BUMPER CENTER BOTTOM COVER GARNISH <i>mc w</i>	1	\$ 360.00	\$ 360.00
19	REAR BUMPER LOWER BRACKET <i>mc w</i>	2	\$ 65.00	\$ 130.00
20	REAR BUMPER REINFORCEMENT <i>Dishbed</i>	1	\$ 899.10	\$ 899.10
21	TAILLAMP <i>could</i>	2	\$ 835.00	\$ 1,670.00

✓ 1350
 ✓ 375
 ✓ 729
 ✓ 750.
 ✓ 340.
 78
 A.
 158
 9560
 472.
 30.
 X.
 -
 +
 X
 X
 ✓
 ✓
 A
 ✓
 ✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNE2299A**
 MODEL : **MERCEDES BENZ GLB200**
 DATE OF ACCIDENT : 19.11.2024
 TIME OF ACCIDENT : 09:50 HOURS

22	TAIL LAMP LOWER BRACKET <i>New</i>	2	\$ 98.00	\$ 196.00
23	REAR FENDER COWLING <i>New</i>	2	\$ 225.00	\$ 450.00
24	REAR WHEEL ARCED GARNISH <i>New torn</i>	2	\$ 329.00	\$ 658.00
25	REAR FENDER INNER TRIM <i>New</i>	2	\$ 520.00	\$ 1,040.00
26	TAIL GATE <i>Dented</i>	1	\$ 3,950.00	\$ 3,950.00
27	TAIL GATE LAMP <i>Crackd</i>	2	\$ 628.00	\$ 1,256.00
28	TAIL GATE LOGO <i>New</i>	1	\$ 86.00	\$ 86.00
29	TAIL GATE LOCK (POWER) <i>Brkd</i>	1	\$ 557.30	\$ 557.30
30	TAIL GATE OUTER SWITCH BUTTOM <i>Brkd</i>	1	\$ 358.20	\$ 358.20
31	TAIL GATE NUMBER PLATE LAMP <i>New</i>	2	\$ 158.20	\$ 316.40
32	TAIL GATE CATCH <i>New</i>	1	\$ 85.00	\$ 85.00
33	TAIL GATE INNER TRIM <i>Crackd</i>	1	\$ 398.00	\$ 398.00
34	TAIL GATE STOPPER <i>New</i>	1	\$ 25.00	\$ 25.00
35	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 365.00	\$ 365.00
36	TAIL GATE DAMPER 'ELETRIC' <i>New</i>	2	\$ 982.00	\$ 1,964.00
37	TAIL GATE AUTO SYSTEM <i>New</i>	1	\$ 3,558.00	\$ 3,558.00
38	REAR END PANEL <i>Dented</i>	1	\$ 2,550.96	\$ 2,550.96
39	REAR END PANEL INNER GARNISH <i>Crackd</i>	1	\$ 369.00	\$ 369.00
40	REAR FLOOR TOP COVER BOARD <i>Dented</i>	1	\$ 658.00	\$ 658.00
41	REAR EXHAUST BOX <i>2</i>	1	\$ 3,566.00	\$ 3,566.00
42	REAR EXHAUST GASKET <i>New</i>	1	\$ 94.00	\$ 94.00
43	REAR EXHAUST INSULATOR <i>New</i>	2	\$ 288.00	\$ 576.00
44	REAR EXHAUST MOUNTING <i>New</i>	4	\$ 150.00	\$ 600.00

16903.20
15212.88

TOTAL PRICE \$ 36,959.16
 LESS 10% \$ 3,695.92
SUB TOTAL PRICE \$ 33,263.24

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 150.00	\$ 150.00
3	REAR BUMPER CENTER WRAPPING <i>New</i>	1	\$ 280.00	\$ 280.00
4	REAR BUMPER DIFESSURE WRAPPING <i>New</i>	1	\$ 450.00	\$ 450.00
3	TAILLAMP CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00
4	TAIL GATE SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNE2299A**
 MODEL : **MERCEDES BENZ GLB200**
 DATE OF ACCIDENT : 19.11.2024
 TIME OF ACCIDENT : 09:50 HOURS

6	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
7	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
8	TAIL GATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
9	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
10	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	<i>60</i>
12	REAR END PANEL TOP GARNISH CLIP <i>new</i>	1	\$ 60.00	\$ 60.00	<i>20</i>

TOTAL \$ 1,860.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>800</i>
3	TUFF COAT	\$ 350.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 180.00	<i>x</i>
6	REMOVE AND REFIX AND RESET TAILGATE AUTO SYSTEM	\$ 250.00	<i>x</i>
7	TRANSFER TAILGATE MECHANISM	\$ 150.00	<i>60</i>
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	<i>120</i>
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	<i>50</i>
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 180.00	<i>50</i>
11	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	<i>50</i>

980

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNE2299A**
MODEL : **MERCEDES BENZ GLB200**
DATE OF ACCIDENT : 19.11.2024
TIME OF ACCIDENT : 09:50 HOURS

12	REMOVE AND REFIX SMART OPEN SENSOR AND DISTANCE SETTING	\$ 180.00	80
13	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 250.00	x
14	RESET BOOTLID SYSTEM	\$ 350.00	x
15	REAR CHASSIS ALIGNMENT	\$ 250.00	x
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 580.00	180

TOTAL \$7,680.00

TOTAL PARTS COST : \$ 35,123.24
TOTAL LABOUR COST : \$ 7,680.00
TOTAL REPAIR COST : \$ 42,803.24

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adnan L
1/5 19/11/24.
07 Days

total 18002.88
C/S 1441C ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: