

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24060292/TNH3E2
Date: 21/08/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SMG7014Z	Insured Vehicle No :	GU1118U
Date of Loss:	26/06/2024	Nature of Claim:	TP
		Claim No:	DMCF2400024H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7014Z	Engine No:	FB20CE07986
Make & Model:	SUBARU XV, 2.0 (A)	Chassis No:	JF1GT7KL5KG061501
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	56583 km
Colour:	Orange		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,996.00	456.00	3,540.00	88.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	3,000.00	1,250.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,246.00	3,456.00	4,790.00	58.09
+ GST 9.00/9.00% (S\$)	742.14	311.04	431.10	58.09
Nett Amount (S\$)	8,988.14	3,767.04	5,221.10	58.09

INSPECTION

Date of Assignment:	27/06/2024	
Date Inspected:	03/07/2024	Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road Singapore 159097
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2024)
Parts:	M1-SUV	SUBARU XV 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG7014Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER F XUV LH	Bent	225.00 FS	*225.00 FS
2	1		*BUMPER PUNCHING F	Not Necessary	642.00 FS	*- FS
3	1		*BRKT CORNER F FHILH	Not Necessary	39.00 FS	*- FS
4	1		*BRKT SD F XUV RH	Not Necessary	8.00 FS	*- FS
5	1		*BRKT SD F XUV LH	Not Necessary	8.00 FS	*- FS
6	1		*COVER FOG F XUV LH	Not Necessary	50.00 FS	*- FS
7	1		*LAMP ASSY HEAD LHS	Not Necessary	2,723.00 FS	*- FS
8	11		*CLIP BMPR	Necessary	33.00 FS	*33.00 FS
9	4		*CLIP	Necessary	16.00 FS	*16.00 FS
10	1		*GARNISH AY FENDERLH	Deformed	152.00 FS	*152.00 FS
11	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,996.00	456.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER & LHS FENDER	New	2,000.00	1,360.00
2	RESPRAY FRONT BUMPER & LHS FENDER	New	1,500.00	1,200.00
3	TO RMV, INSP & TRANSFER FRONT RADIATOR GRILLE AND FOG LAMPS TO NEW BUMPER (S/N)	New	120.00	120.00
4	TO RMV, INSP & REFIT HEADLAMP WASHER, HOSE & RLTD COMP FOR REPAIRS (S/N)	New	180.00	0.00
5	TO RMV & REPLACE ONE LED HEADLAMP WITH CALLIBRATION (S/N)	New	130.00	0.00
6	CARRY OUT DIAGNOSTIC CHECKS & RESET SYSTEMS (S/N)	New	320.00	320.00
Gross Labour Cost (S\$)			4,250.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >