

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0131/2024
DATE : 27-JUN-2024

ECICS LIMITED
10 EUNOS ROAD 8
#09-04A SINGAPORE POST CENTER
S(408600)
TEL : 6337 4779
FAX : 6338 9267

OWNER'S NAME : WAN YI-LING (RUAN YILING) @NURUL SHAZLINA WAN
ADDRESS : APT BLK 8 CHO A CHU KANG GROVE
#07-17
S(688206)
TELEPHONE NO : 9227 1207

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7230115371 AIG
VEHICLE NO : SMG7014Z
MODEL CODE : GT7CKVL
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20CE07986
CHASSIS NO : JF1GT7KL5KG061501
MILEAGE : 1 KM
DATE IN : 27/06/2024
LIABILITY : 0.00
EXCESS CLAUSE : -0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 27/06/2024

Print Date : 27/06/2024
Print Time : 13:47:32

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMG7014Z

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
1	FENDER F XUV LH	57120FL0709P			225.00 <i>bb</i>
2	BUMPER PUNCHING F	57702FL310			642.00 ? XNN
3	BRKT CORNER F FHILH	57707FL010			39.00 ? XNN
4	BRKT SD F XUV RH	57707FL040			8.00 X NN
5	BRKT SD F XUV LH	57707FL050			8.00 ? XNN
6	COVER FOG F XUV LH	57731FL091			50.00 X NN
7	LAMP ASSY HEAD LHS	84002FL110			2723.00 ? XNN
8	CLIP BMPR *11PCS	909140007			33.00 <i>ng</i>
9	CLIP *4PCS	909140062			16.00 <i>nk</i>
10	GARNISH AY FENDERLH	91112FL130			152.00 <i>de</i>
					426
SUB TOTAL			0.00	0.00	3896.00 0.00
LESS DISCOUNT ()			0.00	0.00	0.00 0.00
GRAND TOTAL			0.00	0.00	3896.00 0.00
OVERALL TOTAL			3896.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMG7014Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ECICS INS -GU1118U		
2	ZZ/001	DOA:26/JUN/2024 TIME:1200 HRS LOC:18 BOON LAY WAY OUTSIDE UNIT 05-129		
3	ZZ/002	REPLACE FRONT BUMPER & LHS FENDER 680	2000.00	1360 ✓
4	ZZ/003	RESRPAY FRONT BUMPER & LHS FENDER 600	1500.00	1200 ✓
5	ZZ/004	TO RMV, INSP & TRANSFER FRONT RADIATOR GRILLE AND FOG LAMPS TO NEW BUMPER (S/N)	120.00	✓ ✓
6	ZZ/005	TO RMV, INSP & REFIT HEADLAMP WASHER, HOSE & RLTD COMP FOR REPAIRS (S/N)	180.00	7X NN
7	ZZ/006	TO RMV & REPLACE ONE LED HEADLAMP WITH CALLIBRATION (S/N)	130.00	7X NN
8	ZZ/007	CARRY OUT DIAGNOSTIC CHECKS & RESET SYSTEMS (S/N)	320.00	✓ ✓
9	ZZ/008	SUNDRIES	100.00	30 ✓
		TOTAL LABOUR CHARGES	4350.00	3030

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMG7014Z

TOTAL LABOUR CHARGES	4350.00
TOTAL SPARE PARTS CHARGES	3896.00
GRAND TOTAL	8246.00 *

426
3030
\$3456
4 DAYS #

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Tanji 97495749 / 67563561
w/p 3/7/24 @ 1110am
p/p money before paint
tanji @ 11kanto.com
4 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.