

TP: XE6167C

Make & Model: Hino FS1EKN0 28 TON 6x4 MT

Engine: E13CAT10691

Vehicle: XE6167C Chassis: JHDFSEKNXX10108

Year of Registration: 28/01/2021

Annex A

REPAIR DETAILS

Recommended Parts

S/No.	Qty	Parts Description	Condition	Workshop's Amount (S\$)	Adjuster's Amount (S\$)
1	2	CORNER PANEL COVER LH RH	Deformed	1,124.00	1,124.00
2	2	CORNER PANEL LAMP LH RH	Cracked	716.00	716.00
3	2	CORNER PANEL SIDE RUBBER LH RH	Necessary	170.00	170.00
4	2	CORNER PANEL LOWER RUBBER LH RH	Necessary	190.00	190.00
5	1	SIDE MIRROR ALUMINIUM BRACKET WITH MOTOR RH	Cracked / Missing	1,235.00	1,235.00
6	1	LOWER GRILLE	Missing	875.00	875.00
7	1	LOWER GRILLE PANEL	Missing	1,156.00	1,156.00
8	3	FRONT PANEL LOCK CATCH	Missing	495.00	495.00
9	3	FRONT PANEL LOCK	Missing	555.00	555.00
10	1	FRONT PANEL SHOCK ABSORBER	Bent	500.00	500.00
11	2	AIR HORN	Missing	170.00	170.00
12	1	AIR VALVE VENT	Missing	385.00	385.00
13	1	AIR VALVE ROD	Missing	189.00	189.00
14	3	WIPER MOTOR	Malfunction	1,260.00	1,260.00
15	3	WIPER ARM ASSY WITH WIPER	Bent	750.00	750.00
16	1	BRAKE MASTER AIR VALVE RH	Cracked	1,600.00	1,600.00
17	1	BRAKE FLUID TANK	Cracked	500.00	500.00
18	1	POWER STEERING TANK	Cracked	400.00	400.00
19	1	POWER STEERING BOX ASSY	Cracked	2,000.00	2,000.00
20	1	POWER STEERING SHAFT LOWER	Bent	150.00	150.00
21	1	POWER STEERING SHAFT UPPER	Bent	150.00	150.00
22	1	FRONT CABIN EXTENSION BAR	Bent	600.00	600.00
23	1	VALVE CABIN AIR FRONT	Cracked	350.00	350.00
24	1	DISCHARGE PIPE AND SUCTION HOSE	Bent / Deformed	200.00	200.00
25	1	REVERSE SENSOR	Not Necessary	950.00	-
26	1	RADIATOR COVER BRACKET WITH COW RING	Cracked	1,000.00	1,000.00
27	1	RADIATOR ASSEMBLY	Cracked	700.00	700.00
28	1	TRUNNION BRACKET MIRROR ARM	Bent / Cracked	280.00	280.00
29	1	MIRROR ARM BRACKET UPPER LH	Bent	350.00	350.00
30	1	AIR CONDITIONER COIL SET	Cracked	500.00	500.00
31	1	AIR COND CONDENSER	Bent	300.00	300.00
32	1	GEAR BOX	Cracked	1,200.00	1,200.00
33	1	CUSHION SEAT WITH BRACKET	Not Necessary	1,000.00	-
34	1	CABIN SENSOR	Not Necessary	250.00	-
35	1	MIT CYLINDER HEAD	Dented	900.00	900.00
36	1	STEERING DIESEL PIPE	Bent	120.00	120.00
37	1	ENGINE SIDE COVER - GRILLE BRACKET	Bent	250.00	250.00
38	1	MIRROR ARM MOTOR	Malfunction	350.00	350.00
39	1	TENSIONER	Bent	350.00	350.00
40	2	STEERING PIPE	Deformed	240.00	240.00
41	1	CYLINDER VALVE COVER	Cracked	260.00	260.00
42	1	CYLINDER VALVE HEAD	Cracked	4,000.00	4,000.00
43	1	INTERCOOLER	Deformed	900.00	900.00

Vehicle: XE6167C

Annex A

REPAIR DETAILS

Recommended Parts

S/No.	Qty	Parts Description	Condition	Workshop's Amount (\$\$)	Adjuster's Amount (\$\$)
44	2	MUG GUARD	Deformed	320.00	320.00
45	1	ECG MOTOR	Cracked	1,300.00	1,300.00
46	1	FAN WITH CLUTH	Cut	1,100.00	1,100.00
47	1	H700 HN HOSE WATER	Cut	50.00	50.00
48	1	FAN BELT	Cut	100.00	100.00
49	1	OVERHALL GASKET	Necessary	500.00	500.00
50	1	ENGINE OVERHALL GASKET KIT	Necessary	3,000.00	3,000.00
51	1	RR COMBINATION LAMP ASSY	Cracked	450.00	450.00
52	1	LAMP REVER MT	Cracked	80.00	80.00
53	1	FRONT WINDSHIELD	Cracked	2,000.00	2,000.00
54	1	REAR WINDSHIELD	Cracked	1,500.00	1,500.00
55	1	FRONT & REAR WINDSHIELD MOULDING	Necessary	600.00	600.00
56	2	WINDOW RUBBER SEAL LH/RH	Necessary	350.00	350.00
57	1	FRONT BONNET WITH UPPER GRILLE	Distorted	5,000.00	5,000.00
58	2	SIGNAL LIGHT LH/RH	Not Necessary	400.00	-
59	1	BUMPER	Deformed	3,000.00	3,000.00
60	1	DASH BOARD	Cracked / Deformed	3,000.00	3,000.00
61	1	TAILLAMP RH ASSY	Not Consistent	250.00	-
62	1	TAILLAMP RH BRACKET	Not Consistent	220.00	-
63	1	REAR MUDGUARD PANEL RH	Not Consistent	650.00	-
64	3	REAR MUDGUARD PANEL UPPER BRACKET RH	Not Consistent	540.00	-
65	1	REAR MUDGUARD METAL	Not Consistent	150.00	-
66	1	REAR MUDFLAP RH	Not Consistent	180.00	-
67	1	TAILGATE LOCK RH	Not Consistent	450.00	-
68	1	REAR CHASSIS FRAME SIDE EXTENSION RH	Not Consistent	3,560.00	-
69	1	BADGE, SCANIA LOGO	Necessary	80.00	80.00
70	1	HINO SCUFF PANEL	Necessary	200.00	200.00
71	1	AIR CONDITIONER CONTROL CENTER COVER	Cracked	1,000.00	1,000.00
				59,650.00	51,050.00
				Less 10% (\$\$):	-
				Sub-Total (\$\$):	5,105.00
				59,650.00	45,945.00
<u>Special Nett items</u>					
72	1	REAR TYRE RH	Not Necessary	450.00	-
73	1	REAR WHEEL RIM RH	Not Necessary	650.00	-
74	1	COMPANY STICKERS ASSY	Necessary	800.00	400.00
75	1	BODY SEALANT	Necessary	500.00	400.00
76	1	NUMBER PLATE	Not Necessary	40.00	-
				Sub-Total (\$\$):	800.00
				2,440.00	800.00
				Parts Total (\$\$):	62,090.00
				62,090.00	46,745.00

Vehicle: XE6167C

Annex B

REPAIR DETAILS

Recommended Labour

S/No.	Labour	Workshop's Amount (S\$)	Adjuster's Amount (S\$)
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENT APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT FLOOR PANEL REPAIR, RESHAPE BODY DENTED PANEL IN ACCORDANCE TO FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS	20,000.00	6,000.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	3,000.00	2,700.00
3	TO REMOVE AND REFIT DASHBOARD	400.00	300.00
4	TO CHECK AND RECONNECT WIRING TO ALL NECESSARY COMPONENTS/ATTACHMENTS	3,000.00	300.00
5	SPECIALIST CHARGES - CHECK / DIAGNOSTIC AND REPROGRAMMING	6,000.00	500.00
6	APPLY RUST PROOFING ON ADJACENT PANELS	150.00	150.00
7	TOWING FEES (24FT)	350.00	350.00
Labour Total (S\$):		32,900.00	10,300.00

Annex C

REPAIR DETAILS

Adjusted Repair Cost

	Workshop's Amount (S\$)	Adjuster's Amount (S\$)
Total parts (S\$):	62,090.00	46,745.00
Total labour (S\$):	32,900.00	10,300.00
Total repair cost (S\$):	94,990.00	57,045.00

Adjusted Repair Cost (Lump Sum basis) (S\$)	45,600.00
--	------------------

Vehicle Number: XE6167C



Photo 233 DISMANTLE PHOTO



Photo 234 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 235 DISMANTLE PHOTO



Photo 236 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 237 DISMANTLE PHOTO



Photo 238 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 239 DISMANTLE PHOTO



Photo 240 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 241 DISMANTLE PHOTO



Photo 242 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 243 DISMANTLE PHOTO



Photo 244 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 245 DISMANTLE PHOTO



Photo 246 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 247 DISMANTLE PHOTO



Photo 248 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 249 DISMANTLE PHOTO



Photo 250 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 251 DISMANTLE PHOTO



Photo 252 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 253 DISMANTLE PHOTO



Photo 254 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 255 DISMANTLE PHOTO



Photo 256 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 257 DISMANTLE PHOTO



Photo 258 DISMANTLE PHOTO

Vehicle Number: XE6167C




Photo 259 DISMANTLE PHOTO



Photo 260 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 261 DISMANTLE PHOTO



Photo 262 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 263 DISMANTLE PHOTO



Photo 264 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 265 DISMANTLE PHOTO



Photo 266 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 267 DISMANTLE PHOTO



Photo 268 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 269 DISMANTLE PHOTO



Photo 270 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 271 DISMANTLE PHOTO



Photo 272 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 273 DISMANTLE PHOTO



Photo 274 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 275 DISMANTLE PHOTO



Photo 276 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 277 DISMANTLE PHOTO



Photo 278 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 279 DISMANTLE PHOTO



Photo 280 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 281 DISMANTLE PHOTO



Photo 282 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 283 DISMANTLE PHOTO



Photo 284 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 285 DISMANTLE PHOTO



Photo 286 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 287 DISMANTLE PHOTO



Photo 288 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 289 DISMANTLE PHOTO



Photo 290 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 291 DISMANTLE PHOTO



Photo 292 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 293 DISMANTLE PHOTO



Photo 294 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 295 DISMANTLE PHOTO



Photo 296 DISMANTLE PHOTO

Vehicle Number: XE6167C




Photo 297 DISMANTLE PHOTO



Photo 298 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 299 DISMANTLE PHOTO



Photo 300 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 301 DISMANTLE PHOTO



Photo 302 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 303 DISMANTLE PHOTO



Photo 304 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 305 DISMANTLE PHOTO



Photo 306 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 307 DISMANTLE PHOTO



Photo 308 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 309 DISMANTLE PHOTO



Photo 310 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 311 DISMANTLE PHOTO



Photo 312 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 313 DISMANTLE PHOTO



Photo 314 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 315 DISMANTLE PHOTO



Photo 316 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 317 DISMANTLE PHOTO



Photo 318 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 319 DISMANTLE PHOTO



Photo 320 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 321 DISMANTLE PHOTO



Photo 322 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 323 DISMANTLE PHOTO



Photo 324 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 325 DISMANTLE PHOTO



Photo 326 DISMANTLE PHOTO

Vehicle Number: XE6167C



Photo 327 AFTER PAINT



Photo 328 AFTER PAINT

Vehicle Number: XE6167C



Photo 329 AFTER PAINT



Photo 330 AFTER PAINT

Vehicle Number: XE6167C



Photo 331 AFTER PAINT



Photo 332 AFTER PAINT

Vehicle Number: XE6167C



Photo 333 AFTER PAINT



Photo 334 AFTER PAINT

Vehicle Number: XE6167C



Photo 335 AFTER PAINT



Photo 336 AFTER PAINT

Vehicle Number: XE6167C



Photo 337 AFTER PAINT




Photo 338 AFTER PAINT

Vehicle Number: XE6167C



Photo 339 AFTER PAINT



Photo 340 AFTER PAINT

Vehicle Number: XE6167C



Photo 341 AFTER PAINT



Photo 342 AFTER PAINT

Vehicle Number: XE6167C



Photo 343 AFTER PAINT



Photo 344 AFTER PAINT

Vehicle Number: XE6167C



Photo 345 AFTER PAINT



Photo 346 AFTER PAINT

Vehicle Number: XE6167C



Photo 347 AFTER PAINT



Photo 348 AFTER PAINT