

Not Authenitd
T Boss

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD648R

AAD2411-065

NBV: \$21,313.45

21 NOV 2024

18 NOV 2024

Vehicle No.:
Chassis No.:
Co UEN.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

SHD648R
VF1ABL15AUC283252
200303878K
RENAULT
LATITUDE
16/11/2024
SMC7763R / AUTO GENERAL
30/11/2017

PART	LIST		
1 BUMPER COVER REAR	\$	<i>Tn</i> 561.70	✓
1 BUMPER BRACKET CTR REAR	\$	<i>Rn</i> 98.10	X
1 BUMPER BRACKET SIDE RH REAR	\$	<i>CM</i> 82.10	✓
1 BUMPER RETAINER LH REAR	\$	<i>Rn</i> 54.20	X
1 BUMPER RETAINER RH REAR	\$	<i>CM</i> 59.80	✓
1 BUMPER LOWER REAR	\$	<i>CM</i> 411.90	✓
1 BUMPER BEAM REAR	\$	<i>R</i> 547.80	X
1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50	X
1 BUMPER REFLECTOR RH	\$	<i>Bu</i> 16.60	✓
1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 277.70	✓
1 TAILLAMP RH	\$	<i>Bu</i> 401.40	✓
1 FENDER PANEL REAR RH	\$	<i>Bu</i> 1,933.20	✓
1 WHEELARCH REAR RH	\$	<i>CM</i> 275.40	✓
1 OUTER PANEL REAR (End Panel)	\$	<i>B</i> 745.80	✓
1 OUTER PANEL REAR (End Panel) TRIM	\$	<i>CM</i> 404.56	✓
1 SPARE WHEEL PANEL	\$	<i>R</i> 1,229.40	X
1 BOOT REAR	\$	<i>Bu</i> 1,677.20	✓
1 BOOT FINISHER	\$	<i>Rn</i> 344.70	X
1 BOOT LOCK	\$	<i>R</i> 246.60	X
1 BOOT WEATHERSTRIP	\$	<i>Rn</i> 178.20	X
1 BOOT STRUT LH	\$	<i>Rn</i> 145.10	X
1 BOOT STRUT RH	\$	<i>Rn</i> 145.10	X
1 BOOT HINGE LH	\$	<i>R</i> 254.20	X
1 BOOT HINGE RH	\$	<i>R</i> 254.20	X
1 BOOT BADGE 'RENAULT'	\$	<i>Rn</i> 82.40	✓
1 BOOT BADGE	\$	<i>Rn</i> 95.80	✓
TOTAL	\$	10,637.66	
10%	\$	1,063.77	
	\$	9,573.89	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD648R

AAD2411-065

SPECIAL NETT

1SET PARKING AID	\$	Th	700.00	400sn
1 REAR BUMPER CLIP	\$	na	65.00	✓
1 REAR LH BUMPER RETAINER CLIP	\$	nn	65.00	X
1 REAR RH BUMPER RETAINER CLIP	\$	nn	65.00	X
1 REAR TAIL LAMP CLIP	\$	nn	65.00	X
1 END PANEL INNER TRIM CLIP	\$	na	60.00	✓
1 REAR BUMPER PROTECTOR	\$	NSP	180.00	X
2 WINDSCREEN SEALANT	\$		150.00	40sn
1 WINDSCREEN MOULDING	\$	nn	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	30sn
1 TYRE	\$	280 Pu	350.00	70?sn 196sn
1 RIM	\$	R1	300.00	✓

TOTAL	\$	2,330.00
TOTAL PARTS	\$	11,903.89

LABOUR

To rust-proofing of the affected areas.	\$	600.00	90d
Putty and spray painting of the affected portion.	\$	2,000.00	1100d
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	1200d
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	60d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100d
To reinstall rear bumper parking sensor.	\$	170.00	60d
To check steering geometry and computer wheel alignment	\$	220.00	60d
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL	\$	5,710.00
--------------	-----------	-----------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sdan