



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 718A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	NOT NECESSARY	1,857.00	-
1	FRONT BUMPER	DEFORMED	678.00	678.00
10	FRONT BUMPER CLIPS	NECESSARY	50.00	30.00
1	FRONT BUMPER RETAINER (RHS)	CRACKED	120.00	60.00
1	FRONT BUMPER LOWER LIP	CUT	188.00	188.00
1	FRONT BUMPER TOP RUBBERSTRIP	NOT NECESSARY	110.00	-
1	FRONT RHS FOG LAMP	CRACKED	643.00	455.00
1	FRONT RHS FOG LAMP COVER	DEFORMED	106.00	106.00
1	RHS HEADLAMP	CUT	3,018.00	3,018.00
1	FRONT RHS FENDER	TO REPAIR SEE LABOUR	2,071.00	-
1	FRONT RHS SPLASH SHIELD	NOT NECESSARY	90.00	-
10	FRONT RHS SPLASH SHIELD CLIPS	NOT NECESSARY	50.00	-
1	FRONT RHS DOOR	NOT NECESSARY	2,138.00	-
1	FRONT BUMPER SENSOR	NOT NECESSARY	169.00	-
	LESS 20% DISCOUNT		-2,257.60	-907.00
			9,030.40	3,628.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REMOVE & INSTALL FRONT RHS END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE. INCLUSIVE OF THE REPAIR OF FRONT RHS FENDER.		1,500.00	400.00
	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT RHS DOOR, FRONT RHS FENDER, FRONT BUMPER LOWER LIP.		1,200.00	400.00
	TO REMOVE & TRANSFER RHS & FRONT DOOR TRIM BOARD, DOOR SCREEN, POWER WINDOW & ELECTRICAL WIRINGS & SERVICEABLE FITTINGS TO NEW DOOR & TEST FUNCTION.	NOT NECESSARY	400.00	-
	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTIONS.		150.00	30.00
	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	NOT NECESSARY	280.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE FRONT BUMPER SENSORS & TEST FUNCTION.		150.00	50.00
			3,680.00	880.00
<b>GRAND TOTAL</b>			<b>12,710.40</b>	<b>4,508.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS/SMO24110484/Avp3m4(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.