



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24110485/Uvp3e2
(BUDGET DIRECT INSURANCE)	Date:	10/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 4380X	Veh. Inspected	SLN 9110R
Policy No.	-	Coverage	0
Claim No.	C10033040/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	22/11/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE (A)	C.C	1496
Engine No.	L15B3539147	Year of Reg.	22/05/2017
Chassis No.	GK81007817	Colour	RED
Odometer	131188 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	YOKOHAMA	6
L/H Front Tyre	185/60R15	YOKOHAMA	6
R/H Rear Tyre	185/60R15	YOKOHAMA	6
L/H Rear Tyre	185/60R15	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/11/2024	Inspection Date	22/11/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days