

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Authorized
22/11/24
L/S \$5800
Tel: 96195936
4 days

VEHICLE NUMBER: SKP2995B
MAKE & MODEL: VOLKSWAGEN GOLF

| | | | | |
|---|---------------|----------|--------------------|-----|
| BONNET | But/Buc | 1690.00 | \$2,231.33 | / |
| FRONT BUMPER | Torn | 1203.00 | \$1,631.81 | / |
| FRONT BUMPER RETAINER L/R X2 | MS no o/s n n | 48.00 | \$112.40 | IPC |
| FRONT BUMPER SIDE BRACKET L/R X2 | ^^ | | \$192.24 | X |
| FRONT BUMPER SIDE GRILLE LH | ^^ | | \$86.90 | X |
| FRONT BUMPER CENTRE LOWER GRILLE | ^^ | | \$237.80 | X |
| FRONT BUMPER SPONGE | Torn | | \$96.00 | / |
| FRONT BUMPER REINFORCEMENT | 1 n | | \$891.20 | X |
| HEADLAMP LH | CNE | 1100.00 | \$2,613.53 | / |
| HEADLAMP TOP PANEL LH | ^ | | \$77.31 | X |
| RADIATOR GRILLE | CNE | 602.00 | \$711.23 | / |
| RADIATOR GRILLE LOGO | n n | | \$89.30 | X |
| FRONT SUPPORT PANEL | CNE | 1100.00 | \$1,571.48 | / |
| FRONT FENDER LH | Dy | 512.00 | \$769.10 | / |
| FRONT FENDER INNER SPLASH SHIELD FRONT LH | See | | \$291.46 | X |
| FRONT FENDER INNER SPLASH SHIELD REAR LH | ^^ | | \$194.70 | X |
| FRONT RIM LH | 1 n | | \$1,846.00 | X |
| FRONT LOWER ARM LH | ^^ | | \$678.10 | X |
| FRONT KNUCKLE ARM LH | ^^ | | \$973.25 | X |
| FRONT KNUCKLE BEARING LH | ^^ | | \$851.30 | X |
| FRONT SHOCK ABSORBER LH | ^^ | | \$478.50 | X |
| FRONT Washer tank | Dis | | \$224.60 | / |
| | | | \$16,849.54 | |
| | | Less 10% | \$1,684.95 | |
| | | | \$15,164.59 | |

| | | | | |
|---|------|--|-----------------|----|
| BONNET INSULATOR CLIPS | 1 n | | \$60.00 | X |
| FRONT BUMPER CLIPS | 1 cc | | \$80.00 | 30 |
| RADIATOR GRILLE CLIPS | 1 n | | \$80.00 | X |
| FRONT FENDER INNER SPLASH SHIELD LH CLIPS | 1 n | | \$70.00 | X |
| FRONT TYRE LH | 1 n | | \$350.00 | X |
| | | | \$640.00 | |

| | | | |
|---|-----|------------|-----|
| TO PROVIDE LABOUR, WORKMANSHIP | | \$1,400.00 | 600 |
| TO SPRAY PAINT ON AFFECTED PANELS | | \$1,000.00 | 600 |
| RUST PROOFING | | \$80.00 | |
| TO CHECK FRONT WIRING AND HEADLAMP LEVELING | | \$60.00 | 20 |
| TO REMOVE, REFIT CONDENSER AND TOP UP A/C GAS | | \$150.00 | 100 |
| TO REMOVE, REFIT RADIATOR, TOP UP COOLANT | 1 n | \$150.00 | X |
| TO CONDUCT COMPUTERISE DIAGNOSTIC, RESET AND | 1 n | \$360.00 | X |
| TO CONDUCT WHEEL ALIGNMENT | 1 n | \$120.00 | X |

6575.60
102
5918.04
30
1320
7269.04
5814

TO REMOVE & REPLACE FRONT LEFT TYRE AND BALANCING
TO REMOVE, REFIT AND REPLACE FRONT LEFT UNDERCARRIAGE
PARTS

✓✓ \$80.00 ✓
✓✓ \$280.00 ✓

\$3,680.00

Total

\$19,484.59

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: