



QUOTATION

CODE: T0003
CUSTOMER: SOMPO INSURANCE SINGAPORE PTE LT
ADDRESS: 50 RAFFLES PLACE
#03-03 SINGAPORE LAND TOWER
SINGAPORE 048623

PAGE NO.: 1
DOCUMENT NO.: 1572
DOCUMENT DATE: 11/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: 1
WIP NO.: 22551
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 6461 6555
MODEL: MAZDA3 1.5L SDN HIGH GRADE BLA
CHASSIS NO.: JM6BM42A8G0347351
ENGINE NO.: P520377381
REG NO.: SGP8199R
REGN DATE: 24/11/2016

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	SOMPO TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.	792		792	1,584.00	S
SUB	TO RESPRAY REAR BUMPER.	756		756	1,890.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			150	300.00	S
SUB	SUNDRIES.			neu	50.00	S 20
BFYD-50-221	REAR BUMPER BM/BN W/SENSOR	22/10.1	1.00 1,143.51	*NO STOCK	1,143.51	S 11
BBM4-50-355	RIVET	neu	4.00 3.71	*NO STOCK	14.84	S 11
BHN1-50-021A	GROMMET, SCREW	neu	4.00 2.36	*NO STOCK	9.44	S 11
B45A-56-146A	FASTENER	neu	4.00 2.36	STOCK	9.44	S 11
KD47-67-UC5A	RETAINER REV SENSOR	neu	2.00 15.77	STOCK	31.54	S 11
D350-51-5L0E	REFLECTOR LHR, REFLEX-	11	1.00 55.13	*NO STOCK	55.13	S 11
D350-51-5M0E	REFLECTOR RHR REFLEX-	11	1.00 55.13	STOCK	55.13	S 11
BFYB-50-EL1	COVER(L), TOWING HOOK BM	MIS	1.00 48.13	STOCK	48.13	S 11
BFYB-50-EK1	COVER, TOWING HOOK BM/BN	11	1.00 48.13	*NO STOCK	48.13	S 11
BHN1-50-2J1A	RETAINER LHR BUMPER BM/BN	11	1.00 40.55		40.55	S X

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

Take note that should you decide not to proceed with the repairs, a service quotation fee with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

UKK Auto Consultants hence notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TRANSEUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 6369 3003, BRN: 199103859N, GST Regn. No.: M90364005A

Date: Showrooms & Service Centres :
ZOOM-ZOOM 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417

Not Authorized

neu
means

62563561

take photo before painting.

25/11/24

3 days



QUOTATION

CODE: T0003
CUSTOMER: SOMPO INSURANCE SINGAPORE PTE LT
ADDRESS: 50 RAFFLES PLACE
#03-03 SINGAPORE LAND TOWER
SINGAPORE 048623

PAGE NO.: 2
DOCUMENT NO.: 1572
DOCUMENT DATE: 11/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV: Lee Yao Sheng
CSP/OP CODE: I
DEPT: 22551
WIP NO.:
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 6461 6555
MODEL: MAZDA3 1.5L SDN HIGH GRADE BLA
CHASSIS NO.: JM6BM42A8G0347351
ENGINE NO.: P520377381
REG NO.: SGP8199R
REGN DATE: 24/11/2016

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BHN1-50-2H1A	RETAINER RHR BUMPER BM/BN	1.00	40.55	*NO STOCK	40.55	S X
DFR5-50-251	BRACKET, BUMPER SKYACTIV	1.00	4.64	*NO STOCK	4.64	S X
B45A-50-260	REINFORMENT REAR BM	1.00	576.77	*NO STOCK	576.77	S ?
KD47-67-UC1	6.SENSOR, ULTRASONIC SKYACTIV	2.00	184.59	*NO STOCK	369.18	S ?
BHR1-67-290	CORD, SHORT RR BUMPER BM	1.00	189.14	*NO STOCK	189.14	S ?
GS1D-50-EM1A	TAPE, PROTECTOR	3.00	7.42	STOCK	22.26	S
BHN1-51-153	GASKET(R), RR.COMB. BM/BN	1.00	26.47	STOCK	26.47	S
BHN1-51-163	GASKET(L), RR.COMB. BM/BN	1.00	26.47	STOCK	26.47	S

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	2,711.32	O	-	-	7,115.32	640.38	7,755.70
Surcharge	0.00	S	9.00%	7,115.32	0.00	0.00	0.00
Labour	4,404.00				7,115.32	640.38	7,755.70
Menus	0.00						

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417