

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24110490/AMA3Q2
Date: 20/03/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240046317
Claimant Vehicle No : SMR5479X **Insured Vehicle No :** SLK2112Y
 Date of Loss: 21/11/2024 Nature of Claim: TP Claim No: 1238269076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR5479X**
 Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHX5571
 Reg. Date: 13/01/2020 (Man. Year: 2019) Chassis No: MMBSTA13AKH002482
 Colour: Black Odometer: 212565 km
 Engine Capacity: 1193 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15
 Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
 Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,470.23	7,967.58	4,502.65	36.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	3,840.00	1,340.00	25.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,650.23	11,807.58	5,842.65	33.10
Approved Total (Overridden) (S\$)		9,450.00		
(S\$)	17,650.23	9,450.00	8,200.23	46.46
+ GST 9.00/9.00% (S\$)	1,588.52	850.50	738.02	46.46
Nett Amount (S\$)	19,238.75	10,300.50	8,938.25	46.46
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		11,022.68		
Global Sum Settlement (S\$)		11,000.00		

INSPECTION

Date of Assignment: 26/11/2024
 Date Inspected: 26/11/2024 Inspected At: Modern Automotive Pte Ltd (HQ)
 Estimated Period of Repair: 12.0 days Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	130.20 FL	*- FL
2	1		*REAR BUMPER	Distorted	765.30 FL	*765.30 FL
3	1		*REAR BUMPER SIDE HOLDER	Not Necessary	35.60 FL	*- FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	180.80 FL	*- FL
5	2		*TAILLAMP LH & RH	Cracked	670.80 FL	*670.80 FL
6	2		*TAILLAMP PANEL LH & RH	Buckled	385.00 FL	*385.00 FL
7	1		*REAR END PANEL	Dented	482.90 FL	*482.90 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	174.60 FL	*174.60 FL
9	1		*REAR END PANEL AIR DUCT	Not Necessary	89.60 FL	*- FL
10	1		*REAR END PANEL AIR DUCT COVER	Deformed	83.50 FL	*83.50 FL
11	1		*REAR END PANEL ANTENNA SENSOR	Damaged	165.90 FL	*165.90 FL
12	1		*REAR END PANEL BUZZER SENSOR	Damaged	120.60 FL	*120.60 FL
13	1		*BOOTLID	Distorted	789.90 FL	*789.90 FL
14	1		*BOOTLID LOCK	Damaged	218.50 FL	*218.50 FL
15	1		*BOOTLID WEATHERSTRIPE	Cut	169.50 FL	*169.50 FL
16	1		*BOOTLID OUTER CHROME MOULDING	Cracked	318.50 FL	*318.50 FL
17	2		*BOOTLID HINGE	Bent	384.20 FL	*384.20 FL
18	2		*REAR FENDER LH & RH	Buckled	1,655.00 FL	*1,655.00 FL
19	1		*REAR FENDER INNER TRIM BOARD LH & RH	O/S Deformed	420.40 FL	*210.20 FL
20	2		*REAR FENDER INNER SHIELD LH & RH	Not Necessary	164.20 FL	*- FL
21	1		*REAR WINDSCREEN MOULDING	Necessary	152.20 FL	*152.20 FL
22	1		*SPARE TYRE PANEL	Repair	906.20 FL	*- FL
23	1		*SPARE TYRE PANEL TOP COVER	Torn	185.50 FL	*185.50 FL
24	1		*REAR EXHAUST PIPE	Not Necessary	759.60 FL	*- FL
25	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.60 FL	*- FL
26	1		*REAR EXHAUST PIPE GASKET	Not Necessary	30.90 FL	*- FL
27	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	115.60 FL	*- FL
28	1		*MITSUBISHI LOGO	Necessary	48.90 FL	*48.90 FL
29	1		*ATTRAGE EMBLEM	Necessary	50.60 FL	*50.60 FL
30	1		*MIVEC EMBLEM	Necessary	54.60 FL	*54.60 FL
31	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
32	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
33	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
34	1		*REAR BUMPER LOWER SPOILER	Cracked	1,200.00 FS	*900.00 FS
35	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
38	1		*BOOTLID SURROUND MOULDING	Necessary	100.00 FS	*60.00 FS
39	1		*BOOTLID TOP SPOILER	Repair	800.00 FS	*- FS
40	1		*BOOTLID CAMERA	Not Necessary	480.00 FS	*- FS
41	2		*REAR FENDER SEALANT	Necessary	120.00 FS	*120.00 FS
42	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
43	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
44	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
45	1		*SPARE TYRE PANEL SEALANT	Not Necessary	60.00 FS	*- FS
46	1		*SET SPARE TYRE PANEL INSULATION PAD	Not Necessary	280.00 FS	*- FS
47	1		*CYCLE & CARRIAGE LOGO	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **13,444.70** **8,676.20**
- List Item Discount on L Items 10.00/10.00% (\$\$) 974.47 708.62

Total Parts (\$\$) **12,470.23** **7,967.58**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	2,000.00	1,600.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,800.00	1,600.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE BOOTLID CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY & REAR SEAT	New	300.00	80.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
8	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
9	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
10	TO REMOVE FUEL TANK	New	150.00	80.00
11	TO APPLY TUFF COAT	New	200.00	150.00
Gross Labour Cost (\$\$)			5,180.00	3,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >