

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Daphne

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 26.11.2024
 VEH NO : SMR5479X
 MODEL : Mitsubishi Attrage
 D O A : 21.11.2024
 YR REF : SLK2112Y

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMR5479X (MITSUBISHI ATTRAGE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp <i>new</i>	2	130.20 +
2	Rear Bumper <i>Distorted</i>	1	765.30 ✓
3	Rear Bumper Side Holder <i>new</i>	1	35.60 +
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	180.80 +
5	Taillamp - LH & RH <i>Cracked</i>	2	670.80 ✓
6	Taillamp Panel - LH & RH <i>Buckled</i>	2	385.00 ✓
7	Rear End Panel <i>Dented</i>	1	482.90 ✓
8	Rear End Panel Top Garnish <i>behind</i>	1	174.60 ✓
9	Rear End Panel Air Duct <i>new</i>	1	89.60 +
10	Rear End Panel Air Duct Cover <i>behind</i>	1	83.50 ✓
11	Rear End Panel Antenna Sensor <i>found</i>	1	165.90 ✓
12	Rear End Panel Buzzer Sensor	1	120.60 ✓
13	Bootlid <i>Distorted</i>	1	789.90 ✓
14	Bootlid Lock <i>Dented</i>	1	218.50 ✓
15	Bootlid Weatherstripe <i>cut</i>	1	169.50 ✓
16	Bootlid Outer Chrome Moulding <i>Cracked</i>	1	318.50 ✓
17	Bootlid Hinge <i>Bent</i>	2	384.20 ✓
18	Rear Fender - LH & RH <i>Buckled</i>	2	1,655.00 ✓
19	Rear Fender Inner Trim Board - LH & RH <i>RH behind</i>	2	420.40 <i>210.20</i>
20	Rear Fender Inner Shield - LH & RH <i>new</i>	2	164.20 +
21	Rear Windscreen Moulding <i>new</i>	1	152.20 ✓
22	Spare Tyre Panel <i>Ripped</i>	1	906.20 +
23	Spare Tyre Panel Top Cover <i>torn</i>	1	185.50 ✓
24	Rear Exhaust Pipe <i>?</i>	1	759.60 +
25	Rear Exhaust Pipe Mounting <i>new</i>	1	35.60 +
26	Rear Exhaust Pipe Gasket <i>new</i>	1	30.90 +
27	Rear Exhaust Pipe Heat Shield <i>new</i>	1	115.60 +

28	Mitsubishi Logo	1	48.90 ✓
29	Attrage Emblem	1	50.60 ✓
30	Mivec Emblem	1	54.60 ✓

7086.20

6377.58

Less 10%

\$	9,744.70
	(974.47)
\$	8,770.23

S/NET ITEMS

1	Rear Number Plate	1	\$	30.00 ✓
2	Rear Number Plate Holder	1	\$	30.00 ✓
3	Rear Bumper Clips	1 set	\$	30.00 ✓
4	Rear Bumper Lower Spoiler	1	\$	1,200.00 900.
5	Reverse Sensor	1 set	\$	280.00 200.
6	Rear End Panel Top Garnish Clips	1 set	\$	20.00 ✓
7	Rear End Panel Sealant	1 set	\$	60.00 ✓
8	Bootlid Surround Moulding	1	\$	100.00 60.
9	Bootlid Top Spoiler	1	\$	800.00 X.
10	Bootlid Camera	1	\$	480.00 +
11	Rear Fender Sealant	2	\$	120.00 ✓
12	Rear Fender Inner Trim Board Clips	2 set	\$	60.00 30
13	Rear Fender Inner Shield Clips	2 set	\$	40.00 +
14	Rear Windscreen Sealant	1	\$	60.00 ✓
15	Spare Tyre Panel Sealant	1	\$	60.00 X
16	Spare Tyre Panel Insulation Pad	1 set	\$	280.00 X
17	Cycle & Carriage Logo	1	\$	50.00 ✓
			\$	3,700.00

Total Parts

\$ 12,470.23

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	2,000.00 1600.
2	To putty & spray up paint works	\$	1,800.00 1800
3	To check wiring	\$	50.00 30
4	To remove reverse sensor	\$	100.00 50
6	To remove bootlid camera	\$	100.00 50
7	To remove upholstery & rear seat	\$	300.00 80
8	To transfer bootlid fittings	\$	150.00 80

9	To remove rear windscreen	\$	180.00	120
10	To remover rear exhaust pipe	\$	150.00	X
11	To remove fuel tank	\$	150.00	80
12	To apply tuff coat	\$	200.00	150
Total Labour		\$	5,180.00	
Grand Total		\$	17,650.23	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 11807.58
L/s: 9450.
12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: