



PROFI AUTOMOTIVE

10 Kaki Bukit Road 2 #01-05

First East Centre

Singapore 417868

☎ 94335558

☐ 94335558

profi.automotive@asia.com

not Authorized
du mray

P/P & 600

2 days

28/6/24

QUOTATION

Q0815

DATE

19/08/2024

TOTAL

SGD S\$5,167.00

TO

Auto & General Insurance(Singapore) Pte Ltd || SMH8365Z - Volkswagen Golf GTI

WWZZZ1KZ7W104537

DESCRIPTION		UNIT PRICE	QTY	AMOUNT	
Rear bumper Listed item	R	S\$1,422.00	1	S\$1,422.00	X
Rear bumper lower diffuser Listed item	R	S\$850.00	1	S\$850.00	X
Rear bumper retainer Listed item	11	S\$55.00	2	S\$110.00	X
Rear bumper clip - 1 set Special nett item	1^	S\$65.00	1	S\$65.00	X
Rear reverse sensor Special nett item	11	S\$400.00	1 Set	S\$400.00	X
Rear exhaust pipe Special nett item	11	S\$600.00	1	S\$600.00	X
Joint sealant Special nett item	11	S\$120.00	1	S\$120.00	X
Check rear wiring and lightning system Labour	11	S\$150.00	1	S\$150.00	X

Thanks for your business!

Remove and ^{refix} renew rear reverse sensor Labour	S\$150.00	1	S\$150.00	20
Remove and straighten rear exhaust Labour	S\$150.00	1	S\$150.00	X
Panel beating on affected areas Labour	S\$400.00	1	S\$400.00	180
Spray painting on affected areas Labour	S\$600.00	1	S\$600.00	400
Apply anti-rust on affected areas Labour	S\$150.00	1	S\$150.00	600
TOTAL			SGD S\$5,167.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thanks for your business!