

QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
CONTACT NO.: 65073846
MODEL: Porsche Cayman GTS PDK
CHASSIS NO.: WP0ZZZ98ZFK182868
ENGINE NO.: EF06403
REG NO.: SND7700E
REGN DATE: 12/08/2015

PAGE NO.: 1
DOCUMENT NO.: 721
DOCUMENT DATE: 21/11/2024
POS ID:ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV:
CSP/OP CODE: Muhammad Nur Faiz
DEPT: W
WIP NO.: 31836
REF. NO.: DS/SND7700E/0371
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
				SGD	SGD	
NOTES	TP CLAIM - FIRST CAPITAL	0.00	0.00		0.00	O
INS-PB-(L)	TO REMOVE /REPLACE FRONT BUMPER, FRONT FENDER RH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	5,160.00	1.00		5,160.00	S
INS-PAINT-(L)	TO RESPRAY FRONT BUMPER, FRONT FENDER RH.	2,800.00	1.00		2,800.00	S
INS-PB-(L)	TO CARRY-OUT BODY CAVITY PRESERVATION.	250.00	1.00		250.00	S
INS-PB-(L)	TO REMOVE & REPLACE TURBO COOLER, RADIATOR, CONDENSER AND RADIATOR FAN ASSY.	1,720.00	1.00		1,720.00	S
INS-PB-(L)	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	500.00	1.00		500.00	S
INS-PB-(L)	TO TRANSFER THE FRONT BUMPER SENSORS.	500.00	1.00		500.00	S
INS-PB-(L)	TO SUPPLY & INSTALL THE BODY WRAP STICKER ON AFFECTED AREAS. (PRICE TO BE ADVISE)	1.00	1.00		1.00	S
INS-PB-(L)	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	250.00	1.00		250.00	S
INS-PB-(L)	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	600.00	1.00		600.00	S
INS-PB-(L)	SUNDRIES.	50.00	1.00		50.00	S
981-505-011-73-	FRONTBUMPER	1.00	2,507.10		2,507.10	S
981-505-525-13-OK1	FRONT BUMPER LOWER SPOILER	1.00	868.70		868.70	S
981-505-564-03-OK1	RETAINING FRAME RH	1.00	142.80		142.80	S

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*

**This estimate is valid for a period of thirty (30) days only.*

**Prices are subject to change without prior notice.*

QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
CONTACT NO.: 65073846
MODEL: Porsche Cayman GTS PDK
CHASSIS NO.: WP0ZZZ98ZFK182868
ENGINE NO.: EF06403
REG NO.: SND7700E
REGN DATE: 12/08/2015

PAGE NO.: 2
DOCUMENT NO.: 721
DOCUMENT DATE: 21/11/2024
POS ID: ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV:
CSP/OP CODE: Muhammad Nur Faiz
DEPT: W
WIP NO.: 31836
REF. NO.: DS/SND7700E/0371
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross	GST
					amount	Code
					SGD	SGD
981-505-794-01-	STRUT BRACE	1.00	173.20		173.20	S
981-505-654-03-OK1	SENSOR COVER RH	1.00	214.00		214.00	S
981-606-193-00-OK1	SENSOR	1.00	360.90		360.90	S
7PP-919-133- -	SENSOR GASKET	4.00	6.70		26.80	S
992-807-891- -	FIXING DEVICE	2.00	30.20		60.40	S
981-505-536-00-	FRONT BUMPER RETAINER RH	1.00	30.30		30.30	S
999-190-191-30-	Blind rivet	6.00	8.10		48.60	S
999-591-941-40-	Expansion rivet	6.00	3.10		18.60	S
981-505-707-00-	BRACKET SPACER	2.00	27.90		55.80	S
981-505-761-02-	RETAINER PLATE HEADLIGHT LH	1.00	77.20		77.20	S
981-505-762-02-	RETAINER PLATE HEADLIGHT RH	1.00	77.20		77.20	S
981-503-032-00-GRV	FRONT FENDER RH	1.00	1,966.80		1,966.80	S
991-503-555-00-	BRACKET HEADLIGHT RH	1.00	35.50		35.50	S
991-503-558-00-	FENDER BRACKET RH	1.00	34.30		34.30	S
991-503-441-01-	FENDER STRUT BRACE RH	1.00	51.40		51.40	S
981-575-322-04-1E0	AIR GUIDE CONDENSER RH	1.00	129.40		129.40	S
991-573-111-06-	CONDENSER RH	1.00	944.20		944.20	S
991-573-711-02-	SEALING FRAME RH	1.00	89.00		89.00	S
991-106-132-03-	RADIATOR RH	1.00	2,090.30		2,090.30	S
981-624-935-01-	RADIATOR FAN RH	1.00	1,125.90		1,125.90	S

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*

**This estimate is valid for a period of thirty (30) days only.*

**Prices are subject to change without prior notice.*

QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
CONTACT NO.: 65073846
MODEL: Porsche Cayman GTS PDK
CHASSIS NO.: WP0ZZZ98ZFK182868
ENGINE NO.: EF06403
REG NO.: SND7700E
REGN DATE: 12/08/2015

PAGE NO.: 3
DOCUMENT NO.: 721
DOCUMENT DATE: 21/11/2024
POS ID: ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV:
CSP/OP CODE: Muhammad Nur Faiz
DEPT: W
WIP NO.: 31836
REF. NO.: DS/SND7700E/0371
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
				SGD	SGD	
991-106-156-02-	RADIATOR FAN BRACKET RH	1.00	546.10		546.10	S
991-106-342-00-	AIR GUIDE RADIATOR RH	1.00	101.20		101.20	S
991-106-766-02-	VENT LINE RH	1.00	118.70		118.70	S
000-043-305-15-	ANTIFREEZE COOLANT	6.00	44.70		268.20	S
981-631-264-03-	HEADLIGHT RH	1.00	5,906.20		5,906.20	S
981-631-188-01-	ADDITIONAL HEADLIGHT RH	1.00	643.30		643.30	S
991-631-156-03-	SIGNAL LIGHT RH	1.00	92.90		92.90	S

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-		-	30,636.00	2,757.24	33,393.24
Surcharge	S	9.00%	30,636.00	2,757.24	0.00	0.00	0.00
Labour					Amount Due		
Menus					30,636.00	2,757.24	33,393.24

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*

**This estimate is valid for a period of thirty (30) days only.*

**Prices are subject to change without prior notice.*

** Deposit tax invoice No.:

Eurokars Services Pte Ltd

Customer signature

Authorised signature

Date: _____

Eurokars Aftersales Centre
27A Tanjong Penjuru, Level 5
Singapore 609042

Tel: (65) 6331 0680
Fax: (65) 6331 0690

Co. Regn. No. 198602110Z
GST Regn. No. M90364005A

Website: www.eurokarsservices.com.sg
Page 2 of 2