



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 5591S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER, REAR BUMPER	DENTED/MTG CRACKED	\$612.68	\$612.68
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	BENT	\$419.90	\$419.90
1	COVER, REAR BUMPER, LOWER	DENTED	\$27.93	\$27.93
1	GUARD, REAR BUMPER, CENTER	DENTED/CUT	\$472.19	\$472.19
1	RETAINER, REAR BUMPER SIDE, LH	SERVICEABLE	\$167.48	\$0.00
1	RETAINER, REAR BUMPER SIDE, RH	SERVICEABLE	\$167.48	\$0.00
1	REFLECTOR ASSY, REFLEX, LH	SERVICEABLE	\$49.25	\$0.00
1	REFLECTOR ASSY, REFLEX, RH	SERVICEABLE	\$49.25	\$0.00
1	COVER, FLOOR UNDER, NO.1 LH	SERVICEABLE	\$220.50	\$0.00
1	COVER, FLOOR UNDER, NO.2 LH	SERVICEABLE	\$304.92	\$0.00
1	COVER, REAR FLOOR CTR	SERVICEABLE	\$290.43	\$0.00
1	COVER, DECK TRIM, REAR	SERVICEABLE	\$159.39	\$0.00
1	PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	\$824.46	\$0.00
1	PANEL SUB-ASSY, BACK DOOR	TO REPAIR SEE LABOUR	\$1,443.86	\$0.00
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	SERVICEABLE	\$1,156.89	\$0.00
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	NOT NECESSARY	\$68.88	\$0.00
1	PLATE, BACK DOOR NAME, NO.1	NOT NECESSARY	\$68.88	\$0.00
1	ORNAMENT SUB-ASSY, BACK DOOR	NOT NECESSARY	\$90.30	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$1,648.67)	(\$383.17)
			<b>\$4,946.00</b>	<b>\$1,149.53</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET PARKING AID (SN)	SERVICEABLE	\$700.00	\$0.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$95.00	\$60.00
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$150.00	\$0.00
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	\$200.00	\$0.00
1	WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	\$130.00	\$0.00
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR NO. PLATE (SN)	SERVICEABLE	\$180.00	\$0.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	\$180.00	\$30.00
2	SEAM SEALANT (SN)	NOT NECESSARY	\$250.00	\$0.00
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	\$85.00	\$0.00
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
			\$2,195.00	\$90.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	NOT NECESSARY	\$300.00	\$0.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	NOT NECESSARY	\$380.00	\$0.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BODY LOWER BACK AND PANEL SUB-ASSY, BACK DOOR		\$1,600.00	\$200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	\$380.00	\$0.00
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	\$180.00	\$0.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	NOT NECESSARY	\$250.00	\$0.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$1,600.00	\$220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR		\$170.00	\$50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$10.00
			\$5,030.00	\$480.00
GRAND TOTAL			\$12,171.00	\$1,719.53
RECOMMENDED COST OF REPAIRS				\$1,719.53
Report Ref No: CS/FCI24110494/Knp3e2				

**KSC**

KENNETH KONG SENG CHEONG



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,

Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.